





report date: 2024-03-28

### General information

Make	MINI
Model	COOPER D ONE D
Colour	White
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg



CarCheck.co.uk page 1/10



## Internet history

#### Entry 1

Date 2021-09-07

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



**MOT** history

**MOT test number** 504705001422

**Result** ✓ Passed

Next expiry date 2023-03-09

**MOT #6** 2021-02-26 11:06

**MOT test number** 501499118617

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-02-13 17:56

**MOT test number** 756418699250

**Result** ✓ Passed

MOT #4 2019-03-02 15:13

MOT test number 345091771454

Result \( \sqrt{Passed} \)

**Advice** The vehicle passed the emission test no print out was produced due to low emission 0.50

**Advice** Underside covers fitted

MOT #3 2018-02-13 10:55

**MOT test number** 183967887168

Result \( \sqrt{Passed} \)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

(2.4.G.2)

Advice

CarCheck.co.uk page 3/10



MOT #2 2017-03-03 16:35

**MOT test number** 643006715525

**Result** 
✓ Passed

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

**Advice** (2.4.G.2)

MOT #1 2016-02-29 10:08

**MOT test number** 375044193389

Result \( \sqrt{Passed} \)

Advice

Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
********		
***************************************		
	More info	>
Plate changes  See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK ME	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2013-03-07
Last registration	2022-03-10
Complete history	See info



Registration #1	2013-03-07	22 mi
Registration #2	2016-02-29	34.300 mi
Registration #3	2017-03-03	45.227 mi
Registration #4	2018-02-13	53.689 mi
Registration #5	2019-03-02	63.393 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 10/1

Number of axles 2

**Engine number** 70728575