



report date: 2024-03-28

General information

Make	MAZDA
Model	5 D SPORT
Colour	Silver
Year of manufacture	2011
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-12
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	43
Total items failed	8

MOT #15	2023-07-13 15:48
MOT test number	308618344786
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2023-07-13 14:07
MOT test number	843467729992
Result	✗ Failed
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #13** 2022-07-07 11:58**MOT test number** 134512269128**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2021-06-18 14:06**MOT test number** 804857144885**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2021-06-18 11:03**MOT test number** 605662635397**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Reversing lamp inoperative (4.6.1 (a))**MOT #10** 2020-07-01 13:34**MOT test number** 923131894181**Result** ✓ Passed**MOT #9** 2019-09-25 14:21**MOT test number** 759816891941**Result** ✓ Passed

**MOT #8**

2019-02-21 15:31

**MOT test number**

222828282815

**Result**

✓ Passed

- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Outer Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

**MOT #7**

2019-02-20 17:36

**MOT test number**

901927250472

**Result**

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Outer Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #6** 2018-02-23 15:52**MOT test number** 433100439531**Result** ✓ Passed

- Advice** Nearside Rear Inner Nail in tyre edge
- Advice** Offside Front Outer deep cut in tyre wall
- Advice** Power steering fluid level low, but not below minimum (2.3.1)
- Advice** Rear wiper worn

**MOT #5** 2017-01-27 17:11**MOT test number** 445973125101**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit deep cut in outer wall (4.1.E.1)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Outer deep cut in tyres outer wall

**MOT #4** 2017-01-27 17:11**MOT test number** 206848883582**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit deep cut in outer wall (4.1.E.1)
- Advice** Nearside Rear Outer deep cut in tyres outer wall
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Offside Stop lamp not working (1.2.1b)

**MOT #3** 2015-12-01 13:36**MOT test number** 301636074781**Result** ✓ Passed

- Advice** Oil cap missing
- Advice** Offside Rear nail in tyre outer edge
- Advice** Child seat fitted
- Advice** Nearside Front deep cut in tyre outer wall
- Advice** Nearside Rear nail in tyre inner edge

**MOT #2** 2014-10-31 17:11**MOT test number** 186634404305**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Oil cap missing
- Notice** Nail and deep cut in n/s/r tyre

**MOT #1** 2014-10-30 16:53**MOT test number** 846413404356**Result** ✗ Failed

- Notice** Nail and deep cut in n/s/r tyre
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Notice** Oil cap missing



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✓  
**MOT**  
  
Expires:  
12 July 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-10-31
Last registration	2023-07-13
Complete history	<a href="#">See info</a>



Registration #1	2011-10-31	21 mi
Registration #2	2014-10-30	16.671 mi
Registration #3	2014-10-31	16.671 mi
Registration #4	2015-12-01	21.899 mi
Registration #5	2017-01-27	26.963 mi
Registration #6	2017-01-27	26.963 mi
Registration #7	2018-02-23	31.231 mi
Registration #8	2019-02-20	36.447 mi
Registration #9	2019-02-21	36.447 mi
Registration #10	2019-02-21	36.447 mi
Registration #11	2019-02-21	36.447 mi
Registration #12	2019-02-21	36.447 mi
Registration #13	2019-02-21	36.447 mi
Registration #14	2019-02-21	36.447 mi
Registration #15	2019-02-21	36.447 mi
Registration #16	2019-02-21	36.447 mi
Registration #17	2019-02-21	36.447 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 336510