





report date: 2024-03-28

### General information

Make	FORD
Model	RANGER THUNDER DCB 4X4
Colour	Silver
Year of manufacture	2008
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	154 BHP
Max. torque	380 Nm
Engine capacity	2.953 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/14



report date: 2024-03-28

## **MOT** history

MOT expiry date	2021-07-29
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	54
Total items failed	10

MOT #14		2020-07-30 12:02
MOT test n	umber	801176416280
Result		✓ Passed
Next expir	y date	2021-07-29
<b>Advice</b> (5.3.4 (a) (i)	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting))	g in excessive movement
Advice	Rear Vehicle structure is corroded but structural rigidity is not signifi	cantly reduced (6.1.1 (c) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.1	.1 (c))
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting	in excessive movement (5.3.4

CarCheck.co.uk page 2/14



Fail

AG57BPK

report date: 2024-03-28

**MOT #13** 2020-07-29 11:06 567713016600 **MOT** test number Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) **Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-28

## MOT #12 2019-07-03 12:08

**MOT test number** 652511272588

Result	✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Rear Some lead and lag on brakes
Advice	Rear Brake pipe corroded, covered in grease or other material Two from brake union (1.1.11 (c))
Advice	Both registration plate lamps are slightly dim
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge On 1.6mm (5.2.3 (e))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Spare tyre under inflated
Advice	Steering box has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Both front tyres are wearing on edges

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #11** 2019-07-03 08:49

**MOT test number** 863117053242

Result **X** Failed **Advice** Offside Front Service brake binding but not excessively (1.2.1 (f)) Advice Spare tyre under inflated Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) Minor Offside Obligatory mirror slightly loose (3.3 (b) (i)) **Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i)) Fail Rear Brake pipe excessively corroded One from brake Union (1.1.11 (c)) Advice Both front tyres are wearing on edges **Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f)) Minor Nearside Obligatory mirror slightly loose (3.3 (b) (i)) **Advice** Rear Some lead and lag on brakes Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Nearside Rear Tyre worn close to legal limit/worn on edge On 1.6mm (5.2.3 (e)) Advice Rear Brake pipe corroded, covered in grease or other material Two from brake union (1.1.11 (c)) Advice **Advice** Both registration plate lamps are slightly dim

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #10	2018-07-	25 08:04
MOT test	number 69312	9263883
Result		✓ Passed
Advice	Steering box has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Slight distortion to both headlamp aim	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Some lead and lag on brakes	
Advice	Rear Brake pipe corroded, covered in grease or other material From brake valve (1.1.11 (c)	))
Advice	Spare tyre under inflated	

MOT #9		2017-07-12 09:37
MOT test	number	734950720478
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Items removed from driver's view prior to test	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8		2017-07-12 09:37
MOT test	number	929829435322
Result		<b>X</b> Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Items removed from driver's view prior to test	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Pass wit	h rectification Nearside Headlamp aim too high (1.8)	

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened Inner face (3.5.1i)

**MOT** #6 2016-07-06 14:19 **MOT** test number 319044618394 Result × Failed Offside Track rod end loose Inner (2.2.B.1d) Fail **Advice** Front brake disc worn, pitted or scored, but not seriously weakened Inner face (3.5.1i) Nearside Steering pivot point has excessive play Drop arm ball joint worn (2.2.B.1g) Fail Advice Front Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5

MOT test number

Fesult

Notice High level brake light not connected

2015-07-15 09:41

507276695117

✓ Passed

MOT #4

MOT test number

236804584183

Result

Advice Centre Stop lamp deteriorated, but still visible from a reasonable distance (1.2.1d)

CarCheck.co.uk page 7/14



report date: 2024-03-28

MOT #3	2013-07-30 16:05
MOT test number	798041713222
Result	✓ Passed
MOT #2	2012-03-06 13:37
MOT test number	719716162080
Result	✓ Passed
Notice Slight play in near sidesteering ijoint	

MOT #1	2011-01-29 11:09
MOT test number	969729021056
Result	✓ Passed

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner	history
0	

For how long did the current and previous owner(s) have this FORD? How many owners d Check it in the premium report and see all owner registrations. Download the full report h		ave?
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	NK NY	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-01-28
Last registration	2020-07-30
Complete history	See info



Registration #1	2008-01-28	21 mi
Registration #2	2011-01-29	21.787 mi
Registration #3	2012-03-06	31.920 mi
Registration #4	2013-07-30	40.090 mi
Registration #5	2014-07-03	46.027 mi
Registration #6	2015-07-15	59.478 mi
Registration #7	2016-07-06	68.590 mi
Registration #8	2016-07-08	68.592 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	154670

CarCheck.co.uk page 14/14