





report date: 2024-03-28

General information

Make	MINI
Model	MINI FIRST
Colour	Silver
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	140 Nm at 2.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MAGE	
NACAI	history
141()1	11151 OT V

MOT expiry date	2025-01-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #14	2023-12-28 12:10
MOT test number	790145363019
Result	✓ Passed
Next expiry date	2025-01-04

MOT #13	2022-12-16 10:42
MOT test number	180240063141
Result	✓ Passed

MOT #12	2021-12-17 12:03
MOT test number	150400692526
Result	✓ Passed

MOT #11		2021-12-15 13:56
MOT test	number	498335547996
Result		× Failed
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

MOT #10	2020-12-18 11:56
MOT test number	257676274707
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2019-12-13 15:15

MOT test number 786139426367

MOT #8 2019-12-10 11:36

MOT test number 545557324473

Result X Failed

MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

MAJOR Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))

MAJOR Electronic stability control warning lamp indicates a fault (7.12 (e))

MOT #7 2018-12-19 12:23

MOT test number 980243839185

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Front Exhaust has a minor leak of exhaust gases Leaking From Exhaust Flexible joint (6.1.2 (a))

MOT #6 2018-01-03 09:31

MOT test number 724655884300

Result

Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #5 2017-01-05 11:01

MOT test number 930141088545

Result

Passed

MOT #4 2015-12-11 10:18

MOT test number 482960639892

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2015-01-05 16:27 **MOT test number** 759385005079 Result ✓ Passed MOT #2 2014-11-13 15:41 **MOT** test number 857427314324 Result ✓ Passed MOT #1 2014-11-13 15:41 **MOT test number** 768717914363 Result × Failed Nearside Front Headlamp aim too high (1.8) Pass with rectification Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d) Pass with rectification Offside Front Headlamp aim too high (1.8)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
	-
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here.	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	OK SIES
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

,

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-29
Last registration	2023-12-28
Complete history	See info



Registration #1	2011-09-29	9 mi
Registration #2	2014-11-13	26.856 mi
Registration #3	2015-01-05	26.861 mi
Registration #4	2015-12-11	35.108 mi
Registration #5	2017-01-05	43.378 mi
Registration #6	2018-01-03	53.432 mi
Registration #7	2018-12-19	61.273 mi
Registration #8	2019-12-10	69.627 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number B626J063