



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI DSG SPORT
Colour	Silver
Year of manufacture	-
Top speed	126 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-05-15
Pictures	0
Listing price	View report

source: cargurus.co.uk

**MOT history**

MOT #16	2022-05-13 15:14
MOT test number	174033046174
Result	✓ Passed
Next expiry date	2023-05-12
Advice	Both rear brake disc corroded
Advice	Suspension arm pin or bush worn but not resulting in excessive movement Both front lower rear (5.3.4 (a) (i))

MOT #15	2021-07-13 08:51
MOT test number	404122271120
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside headlamp pattern poor
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2020-07-30 08:58
MOT test number	957243882660
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearmost console bush (5.3.4 (a) (i))

MOT #13	2020-07-30 08:58
MOT test number	337576080748
Result	✗ Failed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rearmost console bush (5.3.4 (a) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #12** 2019-07-01 14:17**MOT test number** 273136787693**Result** ✓ Passed**MOT #11** 2018-07-25 14:04**MOT test number** 228185764504**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10** 2018-07-25 08:43**MOT test number** 659503865939**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2017-07-21 14:57**MOT test number** 491254883909**Result** ✓ Passed**MOT #8** 2017-07-20 08:41**MOT test number** 871245063020**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #7** 2016-07-20 09:36**MOT test number** 910697050331**Result** ✓ Passed**MOT #6** 2015-07-17 12:44**MOT test number** 475778095114**Result** ✓ Passed**MOT #5** 2014-07-04 14:42**MOT test number** 246065184466**Result** ✓ Passed**Notice** Front wiper blades worn**MOT #4** 2013-07-08 15:16**MOT test number** 166059983131**Result** ✓ Passed**MOT #3** 2012-07-09 09:53**MOT test number** 125271092168**Result** ✓ Passed**MOT #2** 2011-07-27 10:05**MOT test number** 386348201489**Result** ✓ Passed**MOT #1** 2010-07-13 13:34**MOT test number** 523154790103**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	DF07HFX
Plate since	2019-06-29
Current registration	DF07HFX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-07-31
Last registration	2022-05-13
Complete history	See info



Registration #1	2007-07-31	14 mi
Registration #2	2010-07-13	40.423 mi
Registration #3	2011-07-27	33.896 mi
Registration #4	2012-07-09	40.667 mi
Registration #5	2013-07-08	53.945 mi
Registration #6	2014-07-04	65.724 mi
Registration #7	2015-07-17	79.158 mi
Registration #8	2016-07-20	97.032 mi
Registration #9	2017-07-20	116.302 mi
Registration #10	2018-05-20	131.377 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2020-05-20	171.377 mi
Registration #13	2021-05-20	191.377 mi
Registration #14	2022-05-20	211.377 mi
Registration #15	2023-05-20	231.377 mi
Registration #16	2024-05-20	251.377 mi
Registration #17	2025-05-20	271.377 mi
Registration #18	2026-05-20	291.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BMM 147760