





report date: 2024-03-29

General information

Make	VAUXHALL
Model	CORSA SE
Colour	White
Year of manufacture	2021
Gearbox	-

Engine & fuel consumption

Engine capacity	1.199 сс
Fuel type	Petrol
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/10




Internet history


Entry 2

Date 2021-06-24

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2021-05-24

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2025-04-29
MOT pass rate	50 %
MOT passed	1
Failed MOT tests	1
Total advice items	3
Total items failed	3

MOT #2	2024-04-24 14:58
MOT test number	385900044757
Result	✓ Passed
Next expiry date	2025-04-29
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #1	2024-04-24 11:19
MOT test number	154662184599
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed 195/55/16 (5.2.3 (d) (ii))	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



DA21UYX

report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

owner motory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Mumber of plates	,
Current registration	NK NK
Plate since	
Current registration	OK OK
Plate since	
	Moro info

CarCheck.co.uk page 7/10



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2021-04-30
Last registration	2024-04-24
Complete history	See info



Registration #1	2021-04-30	20 mi
Registration #2		77,777 46
Registration #3		73.777 66
Registration #4		77.777 66
Registration #5		9.777 es

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	***
Adult	84%
Children	86%
Pedestrian	66%
Safety systems	69%
Overall rating	78%
Video	see crash video



Additional information

Number of seats	5
Engine number	10XVAL0120178 O3P

CarCheck.co.uk page 10/10