



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Silver
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-20
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #21	2024-01-22 14:11
MOT test number	189249998528
Result	✓ Passed
Next expiry date	2025-01-21

MOT #20	2023-01-14 10:50
MOT test number	880858310159
Result	✓ Passed

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #19	2022-01-22 17:18
MOT test number	967806690223
Result	✓ Passed

MOT #18	2022-01-18 15:34
MOT test number	124237136867
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2022-01-18 15:34
MOT test number	848463512452
Result	✗ Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16** 2021-04-20 15:12**MOT test number** 418585461266**Result** ✓ Passed**MOT #15** 2021-04-19 13:25**MOT test number** 478295954863**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #14** 2020-07-29 11:41**MOT test number** 754263172434**Result** ✓ Passed**MOT #13** 2019-04-27 15:11**MOT test number** 282383335515**Result** ✓ Passed**MOT #12** 2018-06-04 10:11**MOT test number** 380742347714**Result** ✓ Passed**MOT #11** 2017-11-13 10:53**MOT test number** 407053823442**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10** 2016-11-14 14:44**MOT test number** 824900034543**Result** ✓ Passed

**MOT #9** 2016-07-23 07:50**MOT test number** 342102462802**Result** ✓ Passed**MOT #8** 2015-08-08 10:13**MOT test number** 305950925406**Result** ✓ Passed**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2015-08-08 10:13**MOT test number** 165190225203**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2014-08-11 13:16**MOT test number** 819023624261**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-06-02 16:39**MOT test number** 647913654124**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2014-06-02 09:34

MOT test number

595873454130

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3**

2013-05-28 15:51

MOT test number

638738043107

Result**✓ Passed****Notice** Offside front tyre slightly worn on both edges**MOT #2**

2012-06-11 14:59

MOT test number

975513862145

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1**

2012-05-31 15:47

MOT test number

129502752131

Result**✗ Failed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	DX09KKO
Plate since	2019-09-29
Current registration	DX09KKO
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-05-28
Last registration	2024-01-22
Complete history	See info



Registration #1	2009-05-28	26 mi
Registration #2	2012-05-31	27.553 mi
Registration #3	2012-06-11	27.553 mi
Registration #4	2013-05-28	39.493 mi
Registration #5	2014-06-02	50.786 mi
Registration #6	2014-06-02	50.786 mi
Registration #7	2014-08-11	52.174 mi
Registration #8	2015-08-08	57.362 mi
Registration #9	2016-07-23	62.479 mi
Registration #10	2016-11-14	62.926 mi
Registration #11	2017-11-13	72.509 mi
Registration #12	2018-05-22	75.277 mi
Registration #13	2018-05-22	75.277 mi
Registration #14	2018-05-22	75.277 mi
Registration #15	2018-05-22	75.277 mi
Registration #16	2018-05-22	75.277 mi
Registration #17	2018-05-22	75.277 mi
Registration #18	2018-05-22	75.277 mi
Registration #19	2018-05-22	75.277 mi
Registration #20	2018-05-22	75.277 mi
Registration #21	2018-05-22	75.277 mi
Registration #22	2018-05-22	75.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462