



**LNI2VSF**

report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	13.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-08-03
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-02
Pictures	62
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-24
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	28
Total items failed	0

MOT #12 2024-03-14 09:47

MOT test number 430282122048

Result ✓ Passed

Next expiry date 2025-03-24

- Advice** Nearside Front Wheel arch cover loose
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

MOT #11 2023-03-16 17:38

MOT test number 845790310764

Result ✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2023-03-16 12:50

**MOT test number**

845733950983

**Result****✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9**

2022-03-14 11:46

**MOT test number**

529282848877

**Result****✓ Passed**

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #8**

2021-03-16 15:34

**MOT test number**

784219562390

**Result****✓ Passed**

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7**

2020-03-19 14:41

**MOT test number**

688004141811

**Result****✓ Passed**

- Advice** Nearside sil plus doors damaged

**MOT #6** 2020-03-19 09:27**MOT test number** 594737408904**Result** ✗ Failed**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside sil plus doors damaged**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2019-03-04 17:04**MOT test number** 850381371347**Result** ✓ Passed**MOT #4** 2018-03-01 16:32**MOT test number** 405899448104**Result** ✓ Passed**Advice** Front number plate is damaged**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2017-03-14 16:37**MOT test number** 913744589844**Result** ✓ Passed**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MOT #2** 2016-03-15 14:06**MOT test number** 181776927574**Result** ✓ Passed



MOT #1	2015-03-20 12:55
MOT test number	315839475094
Result	✓ Passed
<div>Notice Wipers smearing slightly</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
24 March 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	24 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-24
Last registration	2024-03-14
Complete history	<a href="#">See info</a>



Registration #1	2012-03-24	18 mi
Registration #2	2015-03-20	18.878 mi
Registration #3	2016-03-15	24.720 mi
Registration #4	2017-03-14	30.417 mi
Registration #5	2018-03-01	38.053 mi
Registration #6	2019-03-04	46.073 mi
Registration #7	2020-03-19	54.625 mi
Registration #8	2020-03-19	54.625 mi
Registration #9	2020-03-19	54.625 mi
Registration #10	2020-03-19	54.625 mi
Registration #11	2020-03-19	54.625 mi
Registration #12	2020-03-19	54.625 mi
Registration #13	2020-03-19	54.625 mi
Registration #14	2020-03-19	54.625 mi
Registration #15	2020-03-19	54.625 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1490 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBER3113544