



report date: 2024-03-28

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Orange
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history


Entry 1

Date	2022-05-19
Pictures	6
Listing price	View report

I'VE JUST ARRIVED!

This vehicle is fresh in stock and undergoing our strict preparation process.

Contact the dealership for images and more info.



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-02
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	31
Total items failed	0

MOT #16	2023-05-03 11:34
MOT test number	593041763837
Result	✓ Passed
Next expiry date	2024-05-02
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm worn on inner edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Exhaust mounting defective front and rear (6.1.2 (a))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material both rear and both front to rear (1.1.11 (c))

**MOT #15**

2023-05-01 13:41

MOT test number

447037762608

Result

✗ Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Exhaust mounting defective front and rear (6.1.2 (a))**MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm worn on inner edge (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material both rear and both front to rear (1.1.11 (c))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 195/60/15v (5.2.3 (d) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #14**

2022-03-04 16:28

MOT test number

385819555832

Result

✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Exhaust mounting defective rear silencer (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2022-03-04 10:04**MOT test number** 212024676743**Result** ✗ Failed

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Exhaust mounting defective rear silencer (6.1.2 (a))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12 2021-03-11 13:31**MOT test number** 719109986994**Result** ✓ Passed**MOT #11** 2020-03-12 11:43**MOT test number** 292335570480**Result** ✓ Passed

Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

MOT #10 2019-03-13 11:41**MOT test number** 388952530085**Result** ✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9** 2019-03-13 10:06**MOT test number** 938709767611**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2018-03-08 11:48**MOT test number** 798182475937**Result** ✓ Passed**MOT #7** 2017-03-09 12:25**MOT test number** 803371888334**Result** ✓ Passed**MOT #6** 2016-02-25 08:28**MOT test number** 879922979583**Result** ✓ Passed**MOT #5** 2015-03-05 13:19**MOT test number** 976164165083**Result** ✓ Passed**MOT #4** 2014-02-27 11:29**MOT test number** 626938954048**Result** ✓ Passed**MOT #3** 2013-02-18 11:13**MOT test number** 848459543095**Result** ✓ Passed



MOT #2	2012-03-16 12:06
MOT test number	939056372077
Result	✓ Passed

MOT #1	2011-03-02 14:56
MOT test number	347391161018
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
2 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	2 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BF08XWY
Plate since	2019-03-28
Current registration	BF08XWY
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-06
Last registration	2023-05-03
Complete history	See info



Registration #1	2008-03-06	12 mi
Registration #2	2011-03-02	10.961 mi
Registration #3	2012-03-16	19.871 mi
Registration #4	2013-02-18	26.881 mi
Registration #5	2014-02-27	34.308 mi
Registration #6	2015-03-05	41.227 mi
Registration #7	2016-02-25	47.529 mi
Registration #8	2017-03-09	55.001 mi
Registration #9	2018-03-08	61.861 mi
Registration #10	2019-03-08	68.721 mi
Registration #11	2020-03-08	75.581 mi
Registration #12	2021-03-08	82.441 mi
Registration #13	2022-03-08	89.301 mi
Registration #14	2023-03-08	96.161 mi
Registration #15	2024-03-08	103.021 mi
Registration #16	2025-03-08	109.881 mi
Registration #17	2026-03-08	116.741 mi
Registration #18	2027-03-08	123.601 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8A48618