



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA TECH LINE CDTI ECOFLEX S/S
Colour	Grey
Year of manufacture	2015
Top speed	122 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-04
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-06
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #8	2023-06-20 13:03
MOT test number	172149013901
Result	✓ Passed
Next expiry date	2024-07-06

MOT #7	2023-06-15 12:02
MOT test number	976003115808
Result	✗ Failed
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #6	2022-06-24 10:37
MOT test number	133673024685
Result	✓ Passed

MOT #5	2021-07-07 07:26
MOT test number	437973483369
Result	✓ Passed

**MOT #4** 2021-07-06 13:57**MOT test number** 518635128722**Result** ✗ Failed**MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2020-12-19 15:42**MOT test number** 904112426812**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-06-17 10:25**MOT test number** 587750687476**Result** ✓ Passed**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement TRAILING ARM BUSH SPLITTING (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement TRAILING ARM BUSH SPLITTING (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge WORN ON EDGES (5.2.3 (e))**MOT #1** 2018-06-21 15:28**MOT test number** 289874734101**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 THZ3304
Plate since	2024-03-29
Current registration	 THZ3304
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-07
Last registration	2023-06-20
Complete history	See info



Registration #1	2015-05-07	13 mi
Registration #2	2018-06-21	60.967 mi
Registration #3	2019-06-17	72.796 mi
Registration #4	2020-12-19	89.440 mi
Registration #5	2022-06-20	95.277 mi
Registration #6	2023-06-20	95.277 mi
Registration #7	2023-06-20	95.277 mi
Registration #8	2023-06-20	95.277 mi
Registration #9	2023-06-20	95.277 mi
Registration #10	2023-06-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A3151485GWKX0912LVL