



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 300 SWB LR P/V 110
Colour	Grey
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	300 Nm at 2.250 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-23
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-03
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	27
Total items failed	13

MOT #15 2024-01-03 07:08**MOT test number** 971306424127**Result** Passed**Next expiry date** 2025-01-03

- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2023-01-04 07:06**MOT test number** 575826550993**Result** Passed**MOT #13** 2021-11-05 07:14**MOT test number** 375090715571**Result** Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2021-11-05 07:14

MOT test number

178657617200

Result**✗ Failed****Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**MOT #11**

2020-11-05 16:47

MOT test number

275148193956

Result**✓ Passed****Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Advice** Brake pad warning wires not connected**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Reverse lights innop**Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**MOT #10**

2020-11-04 12:14

MOT test number

277804623706

Result**✗ Failed****Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Advice** Brake pad warning wires not connected**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))**Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Reverse lights innop**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #9** 2019-11-06 14:50**MOT test number** 289786057769**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #8** 2019-10-30 11:01**MOT test number** 689493740752**Result** ✗ Failed**Fail** Nearside Rear Direction indicator lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #7** 2018-09-27 11:31**MOT test number** 672707226043**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively x2 (1.1.14 (a) (i))

**MOT #6** 2018-09-26 12:38**MOT test number** 331930342031**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively x2 (1.1.14 (a) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))**MOT #5** 2017-05-09 15:18**MOT test number** 743751285501**Result** ✓ Passed**MOT #4** 2017-05-09 13:58**MOT test number** 774641169418**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Shock absorber insecure (2.7.2b)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #3** 2016-03-21 18:07**MOT test number** 750750783820**Result** ✓ Passed**MOT #2** 2015-03-30 10:45**MOT test number** 426929885087**Result** ✓ Passed**Notice** Emissions to clean to register



MOT #1	2014-03-11 10:27
MOT test number	776870174050
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
3 January 2025

Tax status		Valid until 1 July
Days left		63
MOT expiry date		3 January 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RV11ROU
Plate since	2019-03-28
Current registration	RV11ROU
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-01
Last registration	2024-01-03
Complete history	See info



Registration #1	2011-04-01	26 mi
Registration #2	2014-03-11	44.174 mi
Registration #3	2015-03-30	62.769 mi
Registration #4	2016-03-21	72.748 mi
Registration #5	2017-05-09	82.305 mi
Registration #6	2017-05-09	82.305 mi
Registration #7	2018-09-26	96.875 mi
Registration #8	2018-09-27	96.875 mi
Registration #9	2019-10-30	109.947 mi
Registration #10	2019-10-30	109.947 mi
Registration #11	2019-10-30	109.947 mi
Registration #12	2019-10-30	109.947 mi
Registration #13	2019-10-30	109.947 mi
Registration #14	2019-10-30	109.947 mi
Registration #15	2019-10-30	109.947 mi
Registration #16	2019-10-30	109.947 mi
Registration #17	2019-10-30	109.947 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	2077 mm
Length	4863 mm
Kerb weight	1680 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BY11241