





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|---------------------|
| Model | COUNTRYMAN COOPER S |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 146 mph |
| 0 - 60 mph | 6.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 189 BHP |
|-------------------------|---------------------|
| Max. torque | 280 Nm at 1.250 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 138 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

| Entry | 1 |
|-------|---|
| | |

| Date | 2022-07-08 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/11



PF68LLP report date: 2024-03-29

MOT history

| MOT expiry date | 2024-09-18 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 9 |
| Total items failed | 0 |

| MOT #3 | 2023-09-19 09:14 |
|------------------|------------------|
| MOT test number | 572503837183 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-18 |

| MOT #2 | 2022-08-22 08:49 |
|-----------------|------------------|
| MOT test number | 431747837293 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-11-16 12:50

MOT test number 726537169864

✓ Passed Result **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice Advice** Offside Rear Nail in tyre **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



PF68LLP report date: 2024-03-29

Tax & MOT check



Expires: 18 September 2024

MOT

Tax expired: 1 February 2024

Tax status

Expired at 1 February 2024

Days left 89 days too late

MOT expiry date 18 September 2024

Full MOT history See MOT history

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| \sim | ner | h:- | L |
|-----------|-----|-----|--------------|
| () \ \ \ | ner | nıs | \mathbf{r} |
| | | | |

| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report | | |
|--|-------------|--|
| ******** | | |
| *************************************** | | |
| *************************************** | | |
| manage and a second sec | | |
| *************************************** | | |
| THE PROPERTY OF THE PROPERTY O | | |
| | More info > | |
| Plate changes | | |
| See in this check if this MINI had different number plates. | | |
| Number of plates | | |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK NE | |
| Plate since | | |
| | More info > | |

CarCheck.co.uk page 8/11



PF68LLP report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2018-11-30 |
| Last registration | 2023-09-19 |
| Complete history | See info |



| Registration #1 | 2018-11-30 | 27 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-11-16 | 12.936 mi |
| Registration #3 | | 11.177 es |
| Registration #4 | | 77,777 66 |
| Registration #5 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1727 mm |
|---------------------|---------|
| Height | 1414 mm |
| Length | 3850 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1235 kg |
| Max. allowed weight | 1640 kg |

Additional information

| Fuel tank capacity | 44 | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 4 | page 11/11 |

Number of axles 2

Engine number F779H812