



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Red
Year of manufacture	2014
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-03
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #9	2023-07-04 08:50
MOT test number	426478757086
Result	✓ Passed
Next expiry date	2024-07-03
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8	2023-07-04 08:50
MOT test number	948859466520
Result	✗ Failed
Pass with rectification	Windscreen washer not working (3.5 (a))
Pass with rectification	Horn not working (7.7 (a))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7	2022-04-25 09:32
MOT test number	900007839969
Result	✓ Passed

MOT #6	2021-05-19 14:34
MOT test number	160755716336
Result	✓ Passed

**MOT #5** 2020-09-02 08:00**MOT test number** 845881457503**Result** ✓ Passed**MOT #4** 2020-08-27 11:45**MOT test number** 839143878801**Result** ✗ Failed**Fail** Horn not working (7.7 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #3** 2019-08-10 08:46**MOT test number** 962638262592**Result** ✓ Passed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))**MOT #2** 2018-08-13 08:39**MOT test number** 210337848994**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing h perished (5.2.3 (d) (i))**Advice** Front brake pads look low



MOT #1

2017-08-18 11:22

MOT test number

330965155395

Result

✓ Passed

- Advice

Both rear tyres slight cracking between tread
- Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Nearside Rear Tyre worn close to the legal limit outer edge (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
3 July 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-05
Last registration	2023-07-04
Complete history	See info



Registration #1	2014-09-05	13 mi
Registration #2	2017-08-18	21.919 mi
Registration #3	2018-08-13	28.272 mi
Registration #4	2019-08-10	40.391 mi
Registration #5	2020-08-27	48.446 mi
Registration #6	2020-09-02	48.681 mi
Registration #7	2020-09-02	48.681 mi
Registration #8	2020-09-02	48.681 mi
Registration #9	2020-09-02	48.681 mi
Registration #10	2020-09-02	48.681 mi
Registration #11	2020-09-02	48.681 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1754073