



General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	137 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-07
Pictures	34
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-02
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #11	2024-01-24 16:56
MOT test number	894617291911
Result	✓ Passed
Next expiry date	2025-02-02
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-02-03 18:15
MOT test number	941885039090
Result	✓ Passed

MOT #9	2021-10-23 13:31
MOT test number	436176522208
Result	✓ Passed

MOT #8	2020-11-09 13:37
MOT test number	431659111850
Result	✓ Passed

**MOT #7** 2020-11-09 12:21**MOT test number** 852916143425**Result** ✗ Failed

Fail Nearside Front Headlamp has a product on the light source which changes emitted colour to other than white or yellow (4.1.4 (b))

MOT #6 2019-04-15 14:57**MOT test number** 210551808048**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2018-05-31 11:08**MOT test number** 223758468935**Result** ✓ Passed

Advice Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4 2017-05-26 08:34**MOT test number** 677173284832**Result** ✓ Passed**MOT #3** 2016-05-25 10:14**MOT test number** 647188416263**Result** ✓ Passed



MOT #2	2015-06-01 10:28
MOT test number	366092455125
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2014-05-15 16:00
MOT test number	486455534114
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-05-31
Last registration	2024-01-24
Complete history	See info



Registration #1	2011-05-31	27 mi
Registration #2	2014-05-15	24.588 mi
Registration #3	2015-06-01	42.894 mi
Registration #4	2016-05-25	59.729 mi
Registration #5	2017-05-26	84.206 mi
Registration #6	2018-05-31	106.456 mi
Registration #7	2019-04-15	125.490 mi
Registration #8	2020-05-20	151.277 mi
Registration #9	2021-05-20	151.277 mi
Registration #10	2022-05-20	151.277 mi
Registration #11	2023-05-20	151.277 mi
Registration #12	2024-01-24	151.277 mi
Registration #13	2024-01-24	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1785 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1007260