





report date: 2024-03-29

### General information

Make	NISSAN
Model	LEAF TEKNA
Colour	White
Year of manufacture	2015
Top speed	87 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed automatic

### Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/11




report date: 2024-03-29

### Internet history

### Entry 1

Date 2021-08-10
Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

MOT expiry date	2024-07-19
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #7	2023-07-20 14:53
MOT test number	866857111760
Result	✓ Passed
Next expiry date	2024-07-19
Advice Front Tyre slightly damaged/cracking or perishing Both Sides delamination. (5.2.3 (d) (ii))	

MOT #6		2023-07-20 08:51
MOT test	number	400545658821
Result		<b>X</b> Failed
Fail Front Inner Brake disc in such a condition that it is seriously weakened Both Sides Excessively Surface Corroded. (1.1.14 (a) (ii))		
Advice Front Tyre slightly damaged/cracking or perishing Both Sides delamination. (5.2.3 (d) (ii))		
Advice	Front Inner Brake pad(s) wearing thin Both Sides (1.1.13 (a) (ii))	

MOT #5	2022-07-08 08:22
MOT test	
Result	✓ Passed
Advice (a) (ii))	Front Brake disc worn, pitted or scored, but not seriously weakened Nearside and Offside (1.1.14
<b>Advice</b> (a) (ii))	Rear Brake disc worn, pitted or scored, but not seriously weakened Nearside and Offside (1.1.14

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-07-08 10:21

**MOT test number** 930147749316

Result \rightarrow Passed

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2020-08-05 14:41

MOT test number 309845435339

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

**MOT #2** 2019-08-15 09:05

MOT test number 276639232851

**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-08-28 15:44

**MOT test number** 441053772474

Result \( \sqrt{Passed} \)

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

### Tax & MOT check



Days left 94

MOT expiry date 19 July 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



CP150KA report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



CP150KA report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

CP150KA

report date: 2024-03-29

# For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>.

More info >

# Plate changes

See in this check if this NISSAN had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-26
Last registration	2023-07-20
Complete history	See info



Registration #1	2015-06-26	18 mi
Registration #2	2018-08-28	28.007 mi
Registration #3	2019-08-15	35.792 mi
Registration #4	2020-08-05	40.739 mi
Registration #5	2021-07-08	45.870 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



CP15OKA report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1525 kg
Max. allowed weight	1945 kg

# Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11