



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-09-16
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-15
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-03
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #14	2023-09-29 13:34
MOT test number	706912580051
Result	✓ Passed
Next expiry date	2024-10-03
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #13	2023-09-25 13:58
MOT test number	161380928976
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged slightly out of shape (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure 205/50/17 (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12** 2022-09-21 18:24**MOT test number** 201377172257**Result** ✓ Passed**MOT #11** 2022-09-17 13:09**MOT test number** 425828399246**Result** ✗ Failed**Fail** Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #10** 2021-10-04 12:47**MOT test number** 763882763491**Result** ✓ Passed**Advice** Front Oil leak, but not excessive**MOT #9** 2020-11-13 12:59**MOT test number** 310098837678**Result** ✓ Passed**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2020-11-13 12:59**MOT test number** 263131029713**Result** ✗ Failed**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #7** 2019-11-25 12:16**MOT test number** 885876574581**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Wiper blade a little smeary**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-11-26 14:32**MOT test number** 240708831168**Result** ✓ Passed**MOT #5** 2018-11-26 14:32**MOT test number** 980447911937**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #4** 2017-11-21 12:50**MOT test number** 180329767034**Result** ✓ Passed



MOT #3	2016-11-21 16:45
MOT test number	893505170406
Result	✓ Passed

MOT #2	2015-11-23 10:41
MOT test number	688794974653
Result	✓ Passed
<div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2014-12-08 11:10
MOT test number	609632544380
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
3 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-12-19
Last registration	2023-09-29
Complete history	See info



Registration #1	2011-12-19	26 mi
Registration #2	2014-12-08	20.131 mi
Registration #3	2015-11-23	23.404 mi
Registration #4	2016-11-21	26.596 mi
Registration #5	2017-11-21	29.740 mi
Registration #6	2018-11-26	32.166 mi
Registration #7	2018-11-26	32.166 mi
Registration #8	2019-11-25	35.560 mi
Registration #9	2020-11-13	38.816 mi
Registration #10	2020-11-13	38.816 mi
Registration #11	2020-11-13	38.816 mi
Registration #12	2020-11-13	38.816 mi
Registration #13	2020-11-13	38.816 mi
Registration #14	2020-11-13	38.816 mi
Registration #15	2020-11-13	38.816 mi
Registration #16	2020-11-13	38.816 mi
Registration #17	2020-11-13	38.816 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212