



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI SW SPORT
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-03
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-13
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	50
Total items failed	19

MOT #16	2023-07-14 12:24
MOT test number	364651872538
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15	2023-07-13 10:17
MOT test number	145236471751
Result	✗ Failed
Fail	Nearside Front Suspension arm pin or bush excessively worn wishbone rear bush worn (5.3.4 (a) (i))
Fail	Engine mounting bracket damaged or deteriorated resulting in excessive movement top mount has excessive movement (6.1.8 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn wishbone rear bush worn (5.3.4 (a) (i))

MOT #14	2022-07-04 06:50
MOT test number	668861999462
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #13	2022-06-29 09:12
MOT test number	540293281538
Result	✗ Failed
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Front Brakes imbalanced across an axle (1.2.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2021-05-20 15:42
MOT test number	350047761573
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Brake pad(s) wearing thin nearly worn down to limit. (1.1.13 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-05-20 13:12

MOT test number

372710452160

Result

✗ Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin nearly worn down to limit. (1.1.13 (a) (ii))**Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #10**

2019-05-29 11:05

MOT test number

984288066209

Result

✓ Passed

Advice Service light on**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #9

2018-05-29 15:29

MOT test number

644567061247

Result

✓ Passed

- Advice

Offside front tyre worn on inner edge
- Advice

2 nails in nearside rear tyre one in centre and one on outer edge
- Advice

Handbrake has little reserve travel
- Advice

Nearside front and rear tyre on 3mm
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Engine covers and under trays fitted
- Advice

Nearside front and rear tyre worn on outer edges
- Advice

Front registration plate has slight damage behind screw but not likely to be misread
- Advice

Rear inner brake discs slightly pitted or scored, but not seriously weakened

**MOT #8**

2018-05-29 12:48

MOT test number

443253795767

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear inner brake discs slightly pitted or scored, but not seriously weakened
- Advice** Offside front tyre worn on inner edge
- Advice** 2 nails in nearside rear tyre one in centre and one on outer edge
- Fail** Nearside Rear Position lamp not working (4.2.1 (a))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Handbrake has little reserve travel
- Advice** Nearside front and rear tyre on 3mm
- Advice** Engine covers and under trays fitted
- Advice** Nearside front and rear tyre worn on outer edges
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Front registration plate has slight damage behind screw but not likely to be misread

MOT #7

2017-05-30 11:53

MOT test number

230507961506

Result**✓ Passed**

- Advice** Nearside Front brake warning sensor broken
- Advice** Oil leak
- Advice** Engine light on

**MOT #6** 2017-05-30 11:53**MOT test number** 648308535279**Result** ✗ Failed**Pass with rectification** Headlamp aim too high both (1.8)**Advice** Engine light on**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Oil leak**Advice** Nearside Front brake warning sensor broken**MOT #5** 2016-05-28 09:13**MOT test number** 181607300640**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside rear tyre worn on inner edge**MOT #4** 2015-05-27 10:57**MOT test number** 509007845114**Result** ✓ Passed**Notice** Odf tyre worn heavily on the inner edge**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-05-29 08:42**MOT test number** 287579344463**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-11-21 16:17
MOT test number	307695523381
Result	✓ Passed
<div>Notice Front tyres wearing on outer edges</div>	

MOT #1	2012-12-06 11:18
MOT test number	467521442418
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
13 July 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	BT59EYU
Plate since	2019-03-29
Current registration	BT59EYU
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-12-29
Last registration	2023-07-14
Complete history	See info



Registration #1	2009-12-29	6 mi
Registration #2	2012-12-06	20.040 mi
Registration #3	2013-11-21	26.039 mi
Registration #4	2014-05-29	29.182 mi
Registration #5	2015-05-27	45.740 mi
Registration #6	2016-05-28	63.542 mi
Registration #7	2017-05-30	83.230 mi
Registration #8	2017-05-30	83.230 mi
Registration #9	2018-05-29	102.445 mi
Registration #10	2019-05-29	121.277 mi
Registration #11	2019-05-29	121.277 mi
Registration #12	2019-05-29	121.277 mi
Registration #13	2019-05-29	121.277 mi
Registration #14	2019-05-29	121.277 mi
Registration #15	2019-05-29	121.277 mi
Registration #16	2019-05-29	121.277 mi
Registration #17	2019-05-29	121.277 mi
Registration #18	2019-05-29	121.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1494 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1612 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

DYXH4053089