



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S 5 STR
Colour	Red
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 2

Date	2021-07-02
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-01
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	29
Total items failed	6

MOT #16	2023-07-19 16:24
MOT test number	325020756882
Result	✓ Passed
Next expiry date	2024-07-24
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #15	2023-07-19 10:07
MOT test number	422766160257
Result	✗ Failed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #14** 2022-07-13 10:03**MOT test number** 494146928982**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #13** 2021-07-06 11:55**MOT test number** 587009710412**Result** ✓ Passed**Advice** Covers obscuring some components**MOT #12** 2021-07-02 11:34**MOT test number** 979006186107**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Covers obscuring some components**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Parking brake lever defective so that it cannot be satisfactorily operated (1.1.6 (d))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #11** 2020-06-30 15:59**MOT test number** 864605916467**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #10 2020-06-30 14:03**MOT test number** 269667873248**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))
- Fail** Front Windscreen washer not working (3.5 (a))

MOT #9 2019-06-30 10:11**MOT test number** 771169694730**Result** ✓ Passed**MOT #8** 2018-07-19 07:54**MOT test number** 271976518297**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))

**MOT #7** 2017-07-25 14:24**MOT test number** 294681442875**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Both rear tyres are worn on the inside edges**MOT #6** 2016-06-18 10:31**MOT test number** 141538676458**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-05-09 10:42**MOT test number** 177029225102**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-10-28 08:55**MOT test number** 917261903374**Result** ✓ Passed**Notice** The nearside rear tyre has un-even tread wear on the inside edge**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-11-22 15:10**MOT test number** 985527722379**Result** ✓ Passed



MOT #2	2011-12-03 10:49
MOT test number	135197431330
Result	✓ Passed
<div>Notice</div> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2010-11-04 12:59
MOT test number	992978700375
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-20
Last registration	2023-07-19
Complete history	See info



Registration #1	2007-12-20	23 mi
Registration #2	2010-11-04	27.446 mi
Registration #3	2011-12-03	33.313 mi
Registration #4	2012-11-22	41.731 mi
Registration #5	2013-10-28	53.518 mi
Registration #6	2015-05-09	66.384 mi
Registration #7	2016-06-18	73.996 mi
Registration #8	2017-07-25	82.304 mi
Registration #9	2018-07-19	87.556 mi
Registration #10	2019-06-30	92.582 mi
Registration #11	2020-05-20	95.377 mi
Registration #12	2021-05-20	95.377 mi
Registration #13	2022-05-20	95.377 mi
Registration #14	2023-05-20	95.377 mi
Registration #15	2024-05-20	95.377 mi
Registration #16	2025-05-20	95.377 mi
Registration #17	2026-05-20	95.377 mi
Registration #18	2027-05-20	95.377 mi
Registration #19	2028-05-20	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1472 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	7
Engine number	BSE 497852