






report date: 2024-03-28

## General information

Make	MERCEDES
Model	C C200 K AVANTGARDE SE
Colour	Gold
Year of manufacture	2004
Top speed	144 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.5 mpg
CO2 emission	212 g/km
CO2 label	K



CarCheck.co.uk page 1/16



# Internet history

## Entry 1

Date 2021-12-05

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2024-07-13
MOT pass rate	63 %
MOT passed	17
Failed MOT tests	10
Total advice items	41
Total items failed	7

MOT #27		2023-06-15 14:04
MOT test	number	922973362472
Result		✓ Passed
Next expi	ry date	2024-07-13
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #26		2023-06-14 12:13
MOT test	number	947232206690
Result		<b>X</b> Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (	1.1.14 (a) (ii))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
DANGER	ROUS Front Brake pad(s) less than 1.5 mm thick inners on both front	(1.1.13 (a) (ii))
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	)
DANGER	ROUS Nearside Front Suspension arm ball joint likely to become deta	ched (5.3.4 (a) (ii))

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #25 2022-06-17 14:53

**MOT test number** 739982301099

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #24** 2022-06-15 12:01

**MOT test number** 861302525037

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #23 2021-07-09 15:41

**MOT test number** 179890379461

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22** 2021-07-03 11:23

**MOT test number** 902764682781

**Result** X Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside Rear making noise

CarCheck.co.uk page 4/16



report date: 2024-03-28

2020-07-02 14:41 MOT #21 **MOT test number** 791435022881 Result ✓ Passed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** 

MOT #20		2020-07-01 09:25
MOT test	number	761852685378
Result		<b>×</b> Failed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
MAJOR	Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Advice	Some components on underside of vehicle corroded but not seriously weakend	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
MAJOR	Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))

MOT #19	2019-07-06 13:10
MOT test number	374442417275
Result	✓ Passed

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #18 2018-07-02 16:40 MOT test number 835424405173

**MOT #17** 2018-06-29 16:22

**MOT test number** 103863886913

Result × Failed

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**MOT #16** 2017-06-24 13:55

**MOT test number** 258293768602

Advice Engine management light is on

MOT #15 2016-06-24 10:48

MOT test number 705387603652

Result 

Passed

**Advice** Rear axle and suspension has corrosion

**Advice** Brake pipes and ferrules covered in sealer not allowing full inspection

**Advice** Exhaust bracket at rear broken

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT #14

MOT test number

Result

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

 MOT #13
 2014-07-14 13:56

 MOT test number
 889985794111

 Result
 ✓ Passed

 MOT #12
 2014-07-12 16:09

 MOT test number
 137253294165

 Result
 X Failed

 Fail
 Offside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #11 2013-05-16 16:22
MOT test number 256306433141

Result Passed

MOT #10

MOT test number

489275333169

Result

Kall Offside Front coil spring fractured (2.4.C.1a)

Fail Offside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)

 MOT #9
 2012-05-16 14:52

 MOT test number
 407697332171

 Result
 ✓ Passed

CarCheck.co.uk page 7/16



Result

**KN04TXB** 

report date: 2024-03-28

✓ Passed

MOT #8	2012-05-16 09:31
MOT test number	267547832194
Result	<b>X</b> Failed
Fail Offside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)	

MOT #7	2011-06-22 09:24
MOT test number	639853671189
Result	<b>✓</b> Passed
MOT #6	2010-07-14 12:49
MOT test number	990635090197
Result	✓ Passed
MOT #5	2010-07-13 12:52
MOT test number	800124590144
Result	<b>X</b> Failed
Fail Nearside Front coil spring fractured (2.4.C.1a)	

MOT #4	2009-04-02 11:35
MOT test number	440472699096
Result	✓ Passed
MOT #3	2008-04-11 14:33
MOT test number	210212208163

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #2 2008-04-08 12:35

**MOT test number** 322009598011

Result X Failed

**Fail** Offside Front coil spring fractured (2.4.C.1a)

**Fail** Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

MOT #1 2007-04-12 12:10

**MOT test number** 394532407184

**Result** ✓ Passed

CarCheck.co.uk page 9/16



## Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	13 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.


#### Damage 1

Date
Category
Type
Damage 2
Date

Date

Category

**Type** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

More info >

# Owner history

e mier metery	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK NK
Plate since	

CarCheck.co.uk page 13/16



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 14/16




page 15/16

Mileage check

CarCheck.co.uk

Odometer	In miles
Mileage registrations	29
First mileage registration	2004-04-23
Last registration	2023-06-15
Complete history	See info



Registration #1	2004-04-23	24 mi
Registration #2	2007-04-12	31.125 mi
Registration #3	2008-04-08	41.495 mi
Registration #4	2008-04-11	41.918 mi
Registration #5	2009-04-02	43.976 mi
Registration #6	2010-07-13	46.776 mi
Registration #7	2010-07-14	46.776 mi
Registration #8	2011-06-22	48.384 mi
Registration #9	2012-05-16	49.841 mi
Registration #10	2012-05-16	49.841 mi
Registration #11	2013-05-15	51.447 mi
Registration #12	2013-05-16	51.447 mi
Registration #13	2014-07-12	53.042 mi
Registration #14	2014-07-14	53.042 mi
Registration #15	2015-06-16	54.457 mi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.117 es
Registration #21		11.777 esi
Registration #22		11.177 es
Davistos #22		10.107 au
Registration #23		
Registration #24		0.074
Registration #24		

Registration #27	1.77 40
Registration #28	71,777 66
Registration #29	11.777 es

More info >



# Dimensions & weight

Width	1956 mm
Height	1426 mm
Length	4526 mm
Wheel base	2715 mm
Kerb weight	1970 kg

## Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	27194030315460

CarCheck.co.uk page 16/16