



General information

Make	VOLKSWAGEN
Model	SCIROCCO GTD
Colour	Black
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-08
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-18
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	26
Total items failed	6

MOT #13	2023-07-17 15:16
MOT test number	880963370233
Result	✓ Passed
Next expiry date	2024-07-18
Advice	Front tyres worn inner edges
Advice	Indicator tell tale flashing quicker than normal sequence
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Covers & shields fitted
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #12**

2023-07-12 14:46

MOT test number

349011049247

Result

✗ Failed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Offside Side repeater not working door mirror (4.4.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Covers & shields fitted
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front tyres worn inner edges

MOT #11

2022-07-19 17:44

MOT test number

779497467273

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Suspension components corroded

MOT #10

2021-01-08 14:45

MOT test number

953360687175

Result

✓ Passed

MOT #9

2018-12-05 16:11

MOT test number

122291851634

Result

✓ Passed

- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge Edge wearing thin (5.2.3 (e))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge Edge wearing thin (5.2.3 (e))

**MOT #8** 2018-12-05 12:25**MOT test number** 546410568287**Result** ✗ Failed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge Edge wearing thin (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge Edge wearing thin (5.2.3 (e))**MOT #7** 2017-11-10 14:02**MOT test number** 343484910125**Result** ✓ Passed**MOT #6** 2016-11-05 12:56**MOT test number** 509869630727**Result** ✓ Passed**MOT #5** 2015-11-28 15:15**MOT test number** 738990655141**Result** ✓ Passed**Advice** Child seat fitted**Advice** Under tray fitted**MOT #4** 2015-11-27 11:34**MOT test number** 761660684390**Result** ✗ Failed**Advice** Child seat fitted**Fail** Offside Rear Inner Tyre has ply or cords exposed edge (4.1.D.1b)**Advice** Under tray fitted**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2014-12-09 09:58**MOT test number** 787773344301**Result** ✓ Passed**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2014-02-14 10:33**MOT test number** 547185944009**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Notice** Front discs corroded on inner faces**MOT #1** 2013-02-14 14:35**MOT test number** 709965543091**Result** ✓ Passed**Notice** Scratch across windscreen**Notice** Front fog lamp cracked



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
18 July 2024

Tax status	Expired at 1 April 2024
Days left	27 days too late
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KT10XFD
Plate since	2019-06-29
Current registration	 KT10XFD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-25
Last registration	2023-07-17
Complete history	See info



Registration #1	2010-06-25	28 mi
Registration #2	2013-02-14	40.746 mi
Registration #3	2014-02-14	50.479 mi
Registration #4	2014-12-09	61.635 mi
Registration #5	2015-11-27	66.834 mi
Registration #6	2015-11-28	66.841 mi
Registration #7	2016-11-05	68.920 mi
Registration #8	2017-11-10	82.431 mi
Registration #9	2018-05-20	95.377 mi
Registration #10	2018-05-20	95.377 mi
Registration #11	2018-05-20	95.377 mi
Registration #12	2018-05-20	95.377 mi
Registration #13	2018-05-20	95.377 mi
Registration #14	2018-05-20	95.377 mi
Registration #15	2018-05-20	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CBB319694