





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF GTD DSG
Colour	White
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-02-09
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #8	2023-02-10 07:59
MOT test number	422727445722
Result	✓ Passed
Next expiry date	2024-02-09
Advice Front Inner Brake disc worn, pitted or scored, but not seriously we	akened face (1.1.14 (a) (ii))

MOT #7	2023-02-10 07:59
MOT test number	517520204309
Result	X Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice Front Inner Brak	e disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))

MOT #6	2022-02-10 10:53
MOT test number	790712728780
Result	✓ Passed
MOT #5	2020-11-27 11:34
MOT test number	248249369742
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #4 2019-05-29 12:50

MOT test number 153703861734

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre

Advice Engine cover / under trays fitted

MOT #3 2019-05-24 14:57

MOT test number 314224917643

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Central Exhaust system insecure joint (6.1.2 (a))

Advice Offside Rear Nail in tyre

Advice Engine cover / under trays fitted

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2018-06-01 14:02

MOT test number 562123004591

Result \(\sqrt{Passed} \)


Advice Central Exhaust mounting defective sleeve deteriorated (6.1.2 (a))

CarCheck.co.uk page 4/12



LFZ1757

report date: 2024-03-28



CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 1 March 2024



X MOT

Expired: 9 February 2024

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	9 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date


Category

Type

Damage 2

Date

Category Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many vOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-02-12
Last registration	2023-02-10
Complete history	See info



Registration #1	2010-02-12	9 mi
Registration #2	2018-06-01	54.336 mi
Registration #3	2018-06-01	54.336 mi
Registration #4	2019-05-24	61.962 mi
Registration #5	2019-05-29	61.980 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.77 m
-		11.77 m
Registration #7		11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
CarChack caluk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	CBB 324583