




report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	White
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-08-07
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk





## MOT history

MOT expiry date	2024-06-20
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	18
Total items failed	13

MOT #10	2023-06-09 10:04
MOT test number	302482993842
Result	✓ Passed
Next expiry date	2024-06-20
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2023-06-09 08:30
MOT test number	340912103982
Result	✗ Failed
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-06-04 08:47
MOT test number	430873933734
Result	✓ Passed
Advice	Offside Rear Nail in tyre 2 punctures, one repairable one not



**MOT #7** 2021-06-21 12:10**MOT test number** 322585791949**Result** ✓ Passed**MOT #6** 2021-06-18 15:50**MOT test number** 731575839273**Result** ✗ Failed**Advice** Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #5** 2020-06-11 11:47**MOT test number** 516861141100**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Front Tyre worn on inner edge**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))



**MOT #4** 2020-06-11 10:57**MOT test number** 788870984595**Result** ✗ Failed

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Insecure (6.1.7 (g) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn on inner edge

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**Fail** Front Exhaust system insecure (6.1.2 (a))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking (5.2.3 (d) (ii))

**MOT #3** 2019-06-07 15:24**MOT test number** 889733434115**Result** ✓ Passed**MOT #2** 2019-06-07 12:58**MOT test number** 866805110940**Result** ✗ Failed

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #1** 2018-06-11 11:28**MOT test number** 833669913628**Result** ✓ Passed





Tax & MOT check

X

Untaxed

Tax expired:  
30 March 2024

✓

MOT

Expires:  
20 June 2024

Tax status	Expired at 30 March 2024
Days left	29 days too late
MOT expiry date	20 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX


More info >





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-29
Last registration	2023-06-09
Complete history	<a href="#">See info</a>



Registration #1	2015-05-29	17 mi
Registration #2	2018-06-11	29.213 mi
Registration #3	2019-06-07	38.268 mi
Registration #4	2019-06-07	38.268 mi
Registration #5	2020-06-11	45.678 mi
Registration #6	2020-06-11	45.682 mi
Registration #7	2020-06-11	45.682 mi
Registration #8	2020-06-11	45.682 mi
Registration #9	2020-06-11	45.682 mi
Registration #10	2020-06-11	45.682 mi
Registration #11	2020-06-11	45.682 mi
Registration #12	2020-06-11	45.682 mi

More info >





Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961