





report date: 2024-03-29

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	Grey
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/14



Internet history

Entry 2

Date	2021-06-29
Pictures	1
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-06-29
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-27
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	30
Total items failed	15

MOT #18		2023-07-13 15:54
MOT test	number	207376532232
Result		✓ Passed
Next expi	ry date	2024-07-27
Advice	Exhaust emits blue smoke during acceleration For a few seconds at sta	rt off (8.2.1.2 (g))
Advice	EML Light Illuminated	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #17	2022-07-28 10:10
MOT test number	568522183248
Result	✓ Passed
MOT #16	2022-07-27 14:40
MOT test number	265757004909
Result	× Failed
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #15	2021-07-21 11:03
MOT test number	431380748530
Result	✓ Passed

CarCheck.co.uk page 3/14



DN60WPJ

report date: 2024-03-29

MOT #14 2021-07-14 16:03 MOT test number 608844961985

Result X Failed

Advice Nearside Rear Nail in tyre

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside headlamp fixing broken

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside headlamp fixing broken

Fail Nearside Rear Service brake lagging in operation (1.2.1 (d))

MOT #13 2020-12-17 15:02

MOT test number 799465746049

Result

Passed

Advice Nearside Rear Nail in tyre

MOT #12 2020-12-17 11:44

MOT test number 940007388847

Result × Failed

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Headlamp insecure (4.1.1 (c))

Advice Nearside Rear Nail in tyre

MOT #11 2019-12-05 15:12

MOT test number 342547525122

Result
✓ Passed

CarCheck.co.uk page 4/14



Advice

Fail

DN60WPJ

report date: 2024-03-29

MOT #10

MOT test number

518458685086

Result

Fail Nearside Front Headlamp insecure (4.1.1 (c))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #9

MOT test number

S85523027458

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MOT test number

492999791586

Result

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MOT #7 2017-12-13 12:35 307433073530 **MOT** test number Result ✓ Passed **Advice** Offside rear tyre cracked and perished **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside front tyre cracked and perished Advice Nearside rear tyre has cut on tread face **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14



Advice

Nearside rear tyre has cut on tread face

DN60WPJ

report date: 2024-03-29

MOT #6 2017-12-13 12:35 **MOT** test number 538662725257 Result × Failed **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Pass with rectification Nearside Headlamp insecure (1.7.3) Advice Offside rear tyre cracked and perished Pass with rectification Offside rear brake binding (3.7.B.1) Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice **Advice** Nearside front tyre cracked and perished Pass with rectification Nearside rear brake binding (3.7.B.1)

MOT test number
906807655435

Result
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4

MOT test number

500951512684

Result

Advice Nearside Rear Tyre tread cut, not to cords

CarCheck.co.uk page 6/14



DN60WPJ

report date: 2024-03-29

MOT #3

MOT test number

Passed

Cut in nearside rear tyre tread (not to cords)

MOT test number

Result

Notice Cut in nearside rear tyre tread (not to cords)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1

MOT test number

235698653380

Result

Notice Offside front tyre on 3mm

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



DN60WPJ

report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



More info >

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	NK NK
Plate since	

page 11/14 CarCheck.co.uk



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-01-19
Last registration	2023-07-13
Complete history	See info



Registration #1	2011-01-19	17 mi
Registration #2	2013-12-24	18.933 mi
Registration #3	2014-12-23	23.297 mi
Registration #4	2014-12-23	23.297 mi
Registration #5	2015-12-21	28.039 mi
Registration #6	2016-12-20	30.981 mi
Registration #7	2017-12-13	33.727 mi
Registration #8	2017-12-13	33.727 mi
Registration #9	2018-12-17	35.717 mi
Registration #10	2018-12-17	35.717 mi
Registration #11	2019-12-05	37.860 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		D 277 esc

More info >

page 13/14 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 14/14

Engine number

FJBG1047469