



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Red
Year of manufacture	2008
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-09
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-31
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-15
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	22
Total items failed	4

MOT #19	2023-09-16 09:44
MOT test number	624650382547
Result	✓ Passed
Next expiry date	2024-09-15

MOT #18	2023-09-09 08:19
MOT test number	221063460455
Result	✗ Failed
MAJOR	Nearside Steering rack insecure (2.1.3 (a) (i))
MAJOR	Power steering ram leaking (2.1.5 (a))
MAJOR	Power steering pipe/hose leaking (2.1.5 (a))

MOT #17	2023-08-04 17:08
MOT test number	172576096999
Result	✓ Passed

**MOT #16**

2023-05-16 07:51

MOT test number

317784553555

Result**✗ Failed****MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Power steering component leaking steering rack (2.1.5 (a))**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Windscreen washer not working (3.5 (a))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Play in steering rack inner joint(s)**MOT #15**

2021-10-13 13:39

MOT test number

353980861979

Result**✓ Passed****Advice** Offside Front Slight Play from inner tie rod**MOT #14**

2021-02-17 14:07

MOT test number

661245428642

Result**✓ Passed****Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #13** 2020-02-10 11:12**MOT test number** 571329080166**Result** ✓ Passed**MOT #12** 2020-02-10 10:04**MOT test number** 666463227352**Result** ✗ Failed

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #11 2019-02-12 11:05**MOT test number** 769288969226**Result** ✓ Passed**MOT #10** 2018-02-28 12:29**MOT test number** 313275938247**Result** ✓ Passed**MOT #9** 2018-02-21 10:18**MOT test number** 910133086274**Result** ✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

MOT #8 2017-02-22 09:55**MOT test number** 561503410887**Result** ✓ Passed

**MOT #7** 2016-02-22 11:21**MOT test number** 486515454248**Result** ✓ Passed**Advice** Offside Front tyre wearing on inner edge.**MOT #6** 2015-03-02 16:56**MOT test number** 506751165051**Result** ✓ Passed**MOT #5** 2015-03-02 16:56**MOT test number** 607831865020**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2014-10-15 14:50**MOT test number** 598148884218**Result** ✓ Passed**MOT #3** 2013-10-15 11:52**MOT test number** 476988383231**Result** ✓ Passed**MOT #2** 2012-10-11 11:56**MOT test number** 807725482227**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Small cut in n/s/f tyre wall



MOT #1	2011-08-25 11:48
MOT test number	139017331284
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
15 September 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-10-15
Last registration	2023-09-16
Complete history	See info



Registration #1	2008-10-15	10 mi
Registration #2	2011-08-25	6.863 mi
Registration #3	2012-10-11	13.486 mi
Registration #4	2013-10-15	19.189 mi
Registration #5	2014-10-15	24.914 mi
Registration #6	2015-03-02	26.706 mi
Registration #7	2016-02-22	39.491 mi
Registration #8	2017-02-22	52.328 mi
Registration #9	2018-02-21	64.920 mi
Registration #10	2018-02-28	64.920 mi
Registration #11	2019-02-12	77.026 mi
Registration #12	2019-05-29	91.377 mi
Registration #13	2019-05-29	91.377 mi
Registration #14	2019-05-29	91.377 mi
Registration #15	2019-05-29	91.377 mi
Registration #16	2019-05-29	91.377 mi
Registration #17	2019-05-29	91.377 mi
Registration #18	2019-05-29	91.377 mi
Registration #19	2019-05-29	91.377 mi
Registration #20	2019-05-29	91.377 mi
Registration #21	2019-05-29	91.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8K23159