





report date: 2024-03-28

General information

Make	MAZDA
Model	3 SPORT NAV
Colour	Blue
Year of manufacture	2018
Top speed	123 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2022-07-15

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



LP18UOX report date: 2024-03-28

MOT history

MOT expiry date	2024-08-29
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #5		2023-08-29 16:22
MOT test	number	564018991689
Result		✓ Passed
Next expi	ry date	2024-08-29
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened of	o/s + n/s (1.1.14 (a) (ii))

MOT #4	2023-08-29 15:11	
MOT test number	605051922419	
Result	X Failed	
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened o/s +	n/s (1.1.14 (a) (ii))	

MOT #3		2022-08-30 14:45
MOT test	number	948198452499
Result		✓ Passed
Advice (ii))	Rear Brake disc worn, pitted or scored, but not seriously weakene	ed inner face NS/OS (1.1.14 (a)

CarCheck.co.uk page 3/11



MOT #2

LP18UOX

report date: 2024-03-28

MOT test number 282620327556

Result

X Failed

2022-08-26 15:09

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened inner face NS/OS (1.1.14 (a) (ii))

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1 2021-07-09 13:02

MOT test number 594897959793

Advice Under vehicle covered.

Advice Heavy corrosion on rear brake discs.

CarCheck.co.uk page 4/11



LP18UOX report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



LP18UOX report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

THEFT IN THE STATE OF THE STATE	
Plate changes	More info >
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-08-01
Last registration	2023-08-29
Complete history	See info



Registration #1	2018-08-01	7 mi
Registration #2	2021-07-09	40.765 mi
Registration #3		11.777 es
Registration #4	2022-08-26	56.447 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		10.777 au

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	93%
Children	86%
Pedestrian	65%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1450 mm
Length	4585 mm
Wheel base	2700 mm
Kerb weight	1345 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	PE 21113487

CarCheck.co.uk page 11/11