



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	TUCSON T-GDI GO SE
Colour	Black
Year of manufacture	2018
Top speed	125 mph
0 - 60 mph	8.9 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	175 BHP
Max. torque	265 Nm at 1.500 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.8 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	8
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



## MOT history

MOT expiry date	2025-03-28
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	25
Total items failed	0

MOT #7	2024-03-29 15:48
MOT test number	891847536786
Result	✓ Passed
Next expiry date	2025-03-28

MOT #6	2024-03-26 12:00
MOT test number	914716862671
Result	✗ Failed
<b>DANGEROUS</b> Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>MAJOR</b> Offside Front Road wheel fixing missing (5.2.1 (a) (i))	

MOT #5	2023-03-20 17:35
MOT test number	497953785979
Result	✓ Passed
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Nail in tyre
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Nail in tyre



MOT #4	2023-03-18 15:13
MOT test number	748316844568
Result	✗ Failed
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Nail in tyre
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2022-03-14 14:52
MOT test number	407002830213
Result	✓ Passed

**MOT #2** 2022-03-10 08:39**MOT test number** 431897752118**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Rear Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #1** 2021-01-04 02:09**MOT test number** 947892121652**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
28 March 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	28 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>First licence fee (12 months)</b>	£ 645,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX68XCD
Plate since	2024-03-29
Current registration	EX68XCD
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-09-01
Last registration	2024-03-29
Complete history	<a href="#">See info</a>



Registration #1	2018-09-01	28 mi
Registration #2	2021-01-04	34.295 mi
Registration #3	2022-03-10	44.626 mi
Registration #4	2022-03-14	44.674 mi
Registration #5		
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1850 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1628 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FJJZ586276