



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Black
Year of manufacture	2006
Top speed	129 mph
0 - 60 mph	10.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	192 g/km
CO2 label	J






Internet history

Entry 2

Date	2021-08-08
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-06
Pictures	6
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-11-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	37
Total items failed	7

MOT #15 2021-11-17 10:03

MOT test number 612549080412

Result ✓ Passed

Next expiry date 2022-11-16

- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #14 2020-10-31 12:12

MOT test number 675640609052

Result ✓ Passed

- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13** 2019-04-27 10:45**MOT test number** 320712664847**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Front tyre worn low on inner edge**Advice** Nearside Front tyre worn low on inner edge**Advice** Nearside Rear tyre worn low on outer edge**MOT #12** 2018-05-02 16:35**MOT test number** 710801116724**Result** ✓ Passed**MOT #11** 2018-05-02 09:09**MOT test number** 596647213016**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #10** 2017-04-28 09:10**MOT test number** 736390810144**Result** ✓ Passed**Advice** Nearside steering rack tie rod arm slight play**Advice** Service light illuminated

**MOT #9**

2017-04-27 09:08

MOT test number

929821649477

Result**✗ Failed****Advice** Nearside steering rack tie rod arm slight play**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Service light illuminated**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Outer Drive shaft which forms part of the suspension coupling gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.4.G.4e)**MOT #8**

2016-01-07 09:58

MOT test number

579748792394

Result**✓ Passed****Advice** FRONT NUMBER PLATE DAMAGED**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Advice** MOISTURE IN O/S HEADLAMP**MOT #7**

2014-12-18 09:40

MOT test number

388332654394

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre has few little cuts in tread**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #6** 2014-01-14 11:31**MOT test number** 785624114020**Result** ✓ Passed**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-01-07 16:17**MOT test number** 198317903067**Result** ✓ Passed**Notice** Interior mirror missing**MOT #4** 2012-01-17 12:36**MOT test number** 555567212017**Result** ✓ Passed**MOT #3** 2010-10-12 14:59**MOT test number** 430525380286**Result** ✓ Passed**MOT #2** 2010-10-01 15:31**MOT test number** 903234570261**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1

2009-08-24 12:32

MOT test number

572626439231

Result

✓ Passed

- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Inner rear wheel arches & parts of boot floor covered,vehicle underside dirty.FUEL LOW & WARNING LIGHT ON
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Front brake disc slightly pitted (3.5.1h)
- Notice

Inner front brake pad wear not fully visible,appear low,slight damage yto osr body sill lip,front brake hoses part shrouded,osr tyre odd brand & tread getting low,nsr close to limits & starting to perish,parts of front undertray missing,



Tax & MOT check

✕
Untaxed

Tax expired:
9 August 2022

✕
MOT

Expired:
16 November 2022

Tax status	Expired at 9 August 2022
Days left	628 days too late
MOT expiry date	16 November 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-05-25
Last registration	2021-11-17
Complete history	See info



Registration #1	2006-05-25	11 mi
Registration #2	2009-08-24	23.867 mi
Registration #3	2010-10-01	29.761 mi
Registration #4	2010-10-12	29.763 mi
Registration #5	2012-01-17	34.013 mi
Registration #6	2013-01-07	37.134 mi
Registration #7	2014-01-14	43.194 mi
Registration #8	2014-12-18	50.393 mi
Registration #9	2016-01-07	57.671 mi
Registration #10	2016-05-25	59.377 mi
Registration #11	2016-05-25	59.377 mi
Registration #12	2016-05-25	59.377 mi
Registration #13	2016-05-25	59.377 mi
Registration #14	2016-05-25	59.377 mi
Registration #15	2016-05-25	59.377 mi
Registration #16	2016-05-25	59.377 mi
Registration #17	2016-05-25	59.377 mi
Registration #18	2016-05-25	59.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1543 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH4P1445371