



report date: 2024-03-29

## General information

Make	NISSAN
Model	NOTE ACENTA
Colour	Blue
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	87 BHP
Max. torque	128 Nm at 3.200 rpm
Engine capacity	1.386 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.7 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-21
Pictures	25
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-11-15
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	37
Total items failed	6

MOT #112023-11-16 11:24

MOT test number329681295511

Result✓ Passed

Next expiry date2024-11-15

- Advice**Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice**Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**EXHAUST CORRODED
- Advice**Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive SILL RETURN (5.3.6 (a) (i))
- Advice**Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice**Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice**Rear AXLE CORRODED

**MOT #10**

2022-12-30 13:38

**MOT test number**

285093100868

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive SILL RETURN (5.3.6 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive SILL RETURN (5.3.6 (a) (i))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear AXLE CORRODED

**MOT #9**

2021-12-01 14:16

**MOT test number**

900944002464

**Result**

✓ Passed

- Advice** Rear AXLE BEAM CORRODED
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** EXHAUST SYSTEM CORRODED
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #8**

2021-12-01 10:43

**MOT test number**

548051244209

**Result**

✗ Failed

**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear AXLE BEAM CORRODED**Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** EXHAUST SYSTEM CORRODED**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #7**

2020-12-17 16:44

**MOT test number**

335442795581

**Result**

✓ Passed

**MOT #6**

2019-12-04 12:47

**MOT test number**

409999439585

**Result**

✓ Passed

**MOT #5** 2019-12-04 09:53**MOT test number** 927857344296**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Nearside Front Sub-frame pin or bush excessively worn Rear bush (5.3.4 (a) (i))**MOT #4** 2018-11-23 14:40**MOT test number** 637339059681**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #3** 2017-10-23 09:28**MOT test number** 174363757106**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2016-10-21 08:49**MOT test number** 487409347547**Result** ✓ Passed**MOT #1** 2015-10-17 10:55**MOT test number** 751360499109**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-29
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2012-06-29	25 mi
Registration #2	2015-10-17	26.003 mi
Registration #3	2016-10-21	32.603 mi
Registration #4	2017-10-23	38.462 mi
Registration #5	2018-11-23	43.619 mi
Registration #6	2019-12-04	48.639 mi
Registration #7	2019-12-04	48.640 mi
Registration #8	2019-12-04	48.640 mi
Registration #9	2019-12-04	48.640 mi
Registration #10	2019-12-04	48.640 mi
Registration #11	2019-12-04	48.640 mi
Registration #12	2019-12-04	48.640 mi
Registration #13	2019-12-04	48.640 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1691 mm
Height	1550 mm
Length	4083 mm
Wheel base	2600 mm
Kerb weight	1092 kg
Max. allowed weight	1546 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	326060
---------------	--------