





report date: 2024-03-28

General information

Make	ТОУОТА
Model	RAV-4 VVT-I XT4
Colour	Blue
Year of manufacture	2004
Top speed	109 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	37.2 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 6

Date 2021-08-29

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 5

Date 2021-07-23

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 4

Date 2021-07-03

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

Date carCheck.co.uk 2021-06-19 page 2/14

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-06-05	
------	------------	--

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 20	21-05-21
---------	----------

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk



report date: 2024-03-28

711271214949

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT test number

Advice

MOT expiry date	2025-02-23
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	29
Total items failed	7

MOT #23	2024-02-24 11:13
MOT test number	363919314122
Result	✓ Passed
Next expiry date	2025-02-23
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #22	2023-02-24 16:36
MOT test number	772672235928
Result	✓ Passed
MOT #21	2022-02-11 12:15

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

Rear suspension slightly corroded

MOT #20 2021-02-24 10:49

MOT test number 520521638873

Result 7 Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #19

MOT test number

244751143522

Result

Minor

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice

Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #18

MOT test number

245823900359

Result

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #17 2019-05-24 16:25 663795301518 **MOT** test number Result × Failed Fail Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) **Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) Fail **Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Nearside Front Position lamp not working (4.2.1 (a)) Fail

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number

Result

Minor

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Front offside tyre slight deteriorated

Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #15

MOT test number

562887983404

Result

Advice

Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

Advice

Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

 MOT #14
 2016-07-13 08:59

 MOT test number
 552329392196

 Result
 ✓ Passed

 MOT #13
 2015-07-06 10:28

 MOT test number
 108397485159

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (3.5.1g)

MOT #12

MOT test number

415927685113

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #11 2014-07-07 16:49

MOT test number 188598684106

MOT #10 2014-07-07 16:49

MOT test number 278388384160

Result X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #9 2013-06-28 09:18

MOT test number 277519873452

Result ✓ Passed

MOT #8 2013-06-28 09:18

MOT test number 355599773173

Result × Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)

MOT #7 2012-06-15 09:22

MOT test number 519547062153

Result \(\sqrt{Passed} \)

MOT #6 2011-06-20 12:42

MOT test number 647401171151

MOT #5 2011-06-20 12:42

MOT test number 485691271168

Result X Failed

Pass with rectification Offside Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #4		2010-07-19 16:59
MOT test	number	371670300227
Result		✓ Passed
Advice	Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)	
Notice	Nail in offside rear tyre	
Advice	Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)	
Notice	Drivers sun visor- not staying in the up right postion	
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)	

MOT #3		2009-07-28 11:10
MOT test	number	364749709454
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Front number plate damaged but cannot be misread	
Advice	Rear brake disc slightly pitted (3.5.1h)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2008-08-12 15:05
MOT test number	351245828493
Result	✓ Passed
MOT #1	2007-08-08 09:44
MOT test number	504640427266
Result	✓ Passed
Notice Front number plate cracked	

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner his	ttorv

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

THE PARTY OF THE P	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	AIR SIE
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-08-10
Last registration	2024-02-24
Complete history	See info



Registration #1	2004-08-10	8 mi
Registration #2	2007-08-08	41.077 mi
Registration #3	2008-08-12	50.830 mi
Registration #4	2009-07-28	59.874 mi
Registration #5	2010-07-19	66.060 mi
Registration #6	2011-06-20	71.199 mi
Registration #7	2012-06-15	73.627 mi
Registration #8	2013-06-28	75.897 mi
Registration #9	2014-07-07	77.501 mi
Registration #10	2015-07-06	79.346 mi
Registration #11	2016-07-13	80.878 mi
Registration #12	2017-07-15	82.125 mi
Registration #13	2018-05-21	83.195 mi
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		11.777 es

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/1

Number of axles 2

Engine number 1AZ1443500