



report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ CONVERTIBLE
Colour	Silver
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-04
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	6
Total items failed	16

MOT #22	2023-06-02 11:50
MOT test number	441292418638
Result	✓ Passed
Next expiry date	2024-06-29

MOT #21	2023-06-01 11:27
MOT test number	872682013887
Result	✗ Failed
<div><div>Advice</div> Offside Front Tyre worn close to legal limit/worn on edge outer edge wearing (5.2.3 (e))</div> <div><div>Fail</div> Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))</div> <div><div>Advice</div> Nearside Front Tyre worn close to legal limit/worn on edge outer edge wearing (5.2.3 (e))</div> <div><div>Fail</div> Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))</div>	

MOT #20	2022-06-25 08:47
MOT test number	572316976950
Result	✓ Passed

MOT #19	2021-06-10 14:29
MOT test number	286499954936
Result	✓ Passed

**MOT #18** 2021-06-10 10:32**MOT test number** 172962855401**Result** ✗ Failed

- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Inner Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Brake pipe excessively corroded pipe across front panel corroded / pitted (1.1.11 (c))
- Fail** Nearside Rear Outer Suspension arm pin or bush excessively worn lower arm outer bush (5.3.4 (a) (i))

MOT #17 2020-06-30 07:03**MOT test number** 386023902672**Result** ✓ Passed**MOT #16** 2019-07-04 10:05**MOT test number** 253124583364**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2018-06-12 11:14**MOT test number** 534766143861**Result** ✓ Passed**MOT #14** 2018-06-11 09:40**MOT test number** 653903032674**Result** ✗ Failed

- Fail** Offside Front Brake pipe leaking on an air braking system (1.1.11 (b) (i))

**MOT #13** 2017-06-30 14:41**MOT test number** 860622102560**Result** ✓ Passed**MOT #12** 2017-06-30 08:35**MOT test number** 578665411490**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #11** 2016-06-15 10:41**MOT test number** 429129967133**Result** ✓ Passed**MOT #10** 2016-06-15 10:41**MOT test number** 997361291058**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2015-06-29 10:00**MOT test number** 279050985483**Result** ✓ Passed**MOT #8** 2014-07-04 13:02**MOT test number** 948085284101**Result** ✓ Passed

**MOT #7** 2014-07-03 10:22**MOT test number** 649024584161**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2013-06-18 11:29**MOT test number** 169469463189**Result** ✓ Passed**Notice** FRONT TYRES WEARING ON INNER EDGES**MOT #5** 2012-06-25 15:04**MOT test number** 487437372191**Result** ✓ Passed**MOT #4** 2011-06-22 11:14**MOT test number** 459933271155**Result** ✓ Passed**MOT #3** 2010-06-16 13:40**MOT test number** 920687060136**Result** ✓ Passed**MOT #2** 2010-06-15 14:48**MOT test number** 620426160184**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #1	2009-06-16 13:55
MOT test number	500057569180
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-06-29
Last registration	2023-06-02
Complete history	See info



Registration #1	2006-06-29	26 mi
Registration #2	2009-06-16	22.379 mi
Registration #3	2010-06-15	28.664 mi
Registration #4	2010-06-16	28.665 mi
Registration #5	2011-06-22	34.643 mi
Registration #6	2012-06-25	42.244 mi
Registration #7	2013-06-18	50.267 mi
Registration #8	2014-07-03	58.553 mi
Registration #9	2014-07-04	58.560 mi
Registration #10	2015-06-29	64.554 mi
Registration #11	2016-06-15	71.601 mi
Registration #12	2016-06-15	71.601 mi
Registration #13	2016-06-15	71.601 mi
Registration #14	2016-06-15	71.601 mi
Registration #15	2016-06-15	71.601 mi
Registration #16	2016-06-15	71.601 mi
Registration #17	2016-06-15	71.601 mi
Registration #18	2016-06-15	71.601 mi
Registration #19	2016-06-15	71.601 mi
Registration #20	2016-06-15	71.601 mi
Registration #21	2016-06-15	71.601 mi
Registration #22	2016-06-15	71.601 mi
Registration #23	2016-06-15	71.601 mi
Registration #24	2016-06-15	71.601 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G