



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 16V
Colour	Black
Year of manufacture	2008
Top speed	135 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-07-20
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-24
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-23
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #17	2024-02-20 11:51
MOT test number	222887185656
Result	✓ Passed
Next expiry date	2025-02-23

MOT #16	2024-02-06 16:11
MOT test number	954603157796
Result	✗ Failed
Fail	Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15	2023-02-21 10:14
MOT test number	475793524523
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14** 2022-02-24 10:10**MOT test number** 222674360248**Result** ✓ Passed**MOT #13** 2022-02-24 10:10**MOT test number** 255960331877**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #12** 2021-05-06 12:27**MOT test number** 835215014870**Result** ✓ Passed**MOT #11** 2020-05-07 14:32**MOT test number** 214156468065**Result** ✓ Passed**MOT #10** 2020-05-07 14:32**MOT test number** 177758709986**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Nearside Rear Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #9** 2019-05-15 11:12**MOT test number** 512213491343**Result** ✓ Passed

**MOT #8** 2018-05-10 09:08**MOT test number** 198137663581**Result** ✓ Passed**Advice** Offside Front Lower Tie bar/rod ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Upper Tie bar/rod ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit 3 mm (4.1.E.1)**MOT #7** 2017-05-15 07:44**MOT test number** 919985123078**Result** ✓ Passed**MOT #6** 2016-05-07 09:01**MOT test number** 505865059405**Result** ✓ Passed**MOT #5** 2015-05-11 11:32**MOT test number** 169551035177**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2014-05-27 10:22**MOT test number** 216557444198**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #3	2013-05-24 12:39
MOT test number	708974143162
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2012-05-18 09:12
MOT test number	385449732151
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #1	2011-05-17 11:55
MOT test number	347737631162
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 AF08UHW
Plate since	2019-03-29
Current registration	 AF08UHW
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-30
Last registration	2024-02-20
Complete history	See info



Registration #1	2008-05-30	20 mi
Registration #2	2011-05-17	9.034 mi
Registration #3	2012-05-18	11.125 mi
Registration #4	2013-05-24	13.732 mi
Registration #5	2014-05-27	15.764 mi
Registration #6	2015-05-11	17.063 mi
Registration #7	2016-05-07	18.679 mi
Registration #8	2017-05-15	23.237 mi
Registration #9	2018-05-10	36.922 mi
Registration #10	2019-05-15	51.365 mi
Registration #11	2020-05-20	55.377 mi
Registration #12	2021-05-20	55.377 mi
Registration #13	2022-05-20	55.377 mi
Registration #14	2023-05-20	55.377 mi
Registration #15	2024-05-20	55.377 mi
Registration #16	2025-05-20	55.377 mi
Registration #17	2026-05-20	55.377 mi
Registration #18	2027-05-20	55.377 mi
Registration #19	2028-05-20	55.377 mi
Registration #20	2029-05-20	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17390132