




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 LIFE TDI
Colour	Silver
Year of manufacture	2015
Top speed	106 mph
0 - 100 km/h	13.4 seconds
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-08-16
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-08
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #8 2023-08-23 15:43

MOT test number 473871633244

Result ✓ Passed

Next expiry date 2024-09-08

- Advice** Nearside Rear Inner Brake pad(s) wearing thin pad low (1.1.13 (a) (ii))
- Advice** Nearside Front fog lamp lens cracked
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear discs corroded borderline pass (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 205 x 55 x 16 ...close to 2mm marker bars (5.2.3 (e))
- Advice** Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both rear axle D bushes slight play (5.3.4 (a) (i))

MOT #7 2022-08-09 14:23

MOT test number 848088907374

Result ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and perishing worn on edge (5.2.3 (d) (ii))
- Advice** Nearside Front fog lamp lens cracked

**MOT #6** 2022-08-09 09:13**MOT test number** 770936402044**Result** ✗ Failed**Advice** Nearside Front fog lamp lens cracked**Fail** Suspension arm pin or bush excessively worn both front arms rear bushes (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and perishing worn on edge (5.2.3 (d) (ii))**MOT #5** 2021-09-09 14:26**MOT test number** 956710345008**Result** ✓ Passed**MOT #4** 2021-02-08 11:10**MOT test number** 376719174898**Result** ✓ Passed**MOT #3** 2020-03-05 14:28**MOT test number** 984662613238**Result** ✓ Passed**MOT #2** 2019-05-08 10:56**MOT test number** 354196978530**Result** ✓ Passed**MOT #1** 2018-06-19 10:52**MOT test number** 591303117406**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	8 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXX
Plate since	2024-03-28
Current registration	 XXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-01
Last registration	2023-08-23
Complete history	See info



Registration #1	2015-09-01	24 mi
Registration #2	2018-06-19	57.552 mi
Registration #3	2019-05-08	76.188 mi
Registration #4	2020-03-05	91.124 mi
Registration #5	2021-02-08	94.565 mi
Registration #6	2022-05-20	95.277 mi
Registration #7	2022-05-20	95.277 mi
Registration #8	2022-05-20	95.277 mi
Registration #9	2022-05-20	95.277 mi
Registration #10	2023-08-23	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1861 mm
Length	4876 mm
Wheel base	3006 mm
Kerb weight	1751 kg
Max. allowed weight	2345 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CAYDAP6403