



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D GX
Colour	Green
Year of manufacture	2001
Top speed	106 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.8 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J






Internet history

Entry 2

Date	2021-07-08
Pictures	24
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2025-05-11
MOT pass rate	73 %
MOT passed	19
Failed MOT tests	7
Total advice items	52
Total items failed	18

MOT #26 2024-04-19 15:20**MOT test number** 648651753357**Result** Passed**Next expiry date** 2025-05-11**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #25** 2024-04-19 09:44**MOT test number** 974227030574**Result** Failed**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #24**

2023-05-12 14:27

MOT test number

640898768907

Result

✓ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #23

2022-04-26 14:03

MOT test number

439763457068

Result

✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #22

2022-04-25 11:29

MOT test number

555675567104

Result

✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))

**MOT #21** 2021-04-29 13:59**MOT test number** 877495455323**Result** ✓ Passed

Advice Headlamp has a product on the lens but not seriously reducing light output both headlamp lenses fogging (4.1.4 (b))

MOT #20 2020-02-26 16:49**MOT test number** 125607578377**Result** ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #19 2020-02-26 10:42**MOT test number** 959818956659**Result** ✗ Failed

Fail Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Minor Headlamp lens slightly defective both hazy (4.1.1 (b) (i))

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #18**

2019-03-04 11:34

MOT test number

615476950845

Result

✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear & offside front brake disc splash guards corroded**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #17**

2018-01-29 11:42

MOT test number

624542192629

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #16**

2017-03-09 09:28

MOT test number

560916890785

Result

✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #15**

2017-02-27 17:09

MOT test number

977432658643

Result**✗ Failed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #14**

2016-09-19 14:12

MOT test number

331943073133

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit 2mm 215/70R16 100S (4.1.E.1)**Advice** Body has slight corrosion (6.1.B.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Headlamp deteriorated but light output not reduced Both fronts. (1.7.5a)**Advice** Offside Front Tyre worn close to the legal limit 2mm. 215/70R16 100S (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a pin/bush Lower arm rear bush. (2.4.G.2)

**MOT #13** 2016-09-19 14:12**MOT test number** 602005784796**Result** ✗ Failed

- Advice** Front Headlamp deteriorated but light output not reduced Both fronts. (1.7.5a)
- Advice** Offside Front Tyre worn close to the legal limit 2mm. 215/70R16 100S (4.1.E.1)
- Advice** Offside Front Suspension arm has slight play in a pin/bush Lower arm rear bush. (2.4.G.2)
- Pass with rectification** Headlamp aim too high (1.8)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm 215/70R16 100S (4.1.E.1)
- Advice** Body has slight corrosion (6.1.B.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #12 2015-09-25 15:16**MOT test number** 219537879188**Result** ✓ Passed**MOT #11** 2014-09-25 10:17**MOT test number** 829938564257**Result** ✓ Passed**MOT #10** 2013-09-19 11:09**MOT test number** 289792863280**Result** ✓ Passed**MOT #9** 2012-09-14 15:40**MOT test number** 208908552283**Result** ✓ Passed

**MOT #8** 2011-09-07 11:53**MOT test number** 268380851285**Result** ✓ Passed**MOT #7** 2010-09-28 15:33**MOT test number** 643821570297**Result** ✗ Failed**Pass with rectification** Upper Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #6** 2010-09-28 15:33**MOT test number** 854671370263**Result** ✓ Passed**MOT #5** 2009-09-22 11:33**MOT test number** 360185269459**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Notice** Front pads wearing low**MOT #4** 2009-09-22 11:33**MOT test number** 991975269221**Result** ✓ Passed**Notice** Front pads wearing low**MOT #3** 2008-08-29 16:33**MOT test number** 611552748285**Result** ✓ Passed



MOT #2	2007-08-24 14:01
MOT test number	484166537231
Result	✓ Passed

MOT #1	2006-08-26 09:44
MOT test number	240768636286
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
11 May 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	11 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2001-12-31
Last registration	2024-04-19
Complete history	See info



Registration #1	2001-12-31	15 mi
Registration #2	2006-08-26	20.844 mi
Registration #3	2007-08-24	25.962 mi
Registration #4	2008-08-29	30.094 mi
Registration #5	2009-09-22	46.335 mi
Registration #6	2010-09-28	57.834 mi
Registration #7	2011-09-07	66.142 mi
Registration #8	2012-09-14	76.042 mi
Registration #9	2013-09-19	86.205 mi
Registration #10	2014-09-25	95.795 mi
Registration #11	2015-09-25	104.428 mi
Registration #12	2016-09-19	113.449 mi
Registration #13	2016-09-19	113.449 mi
Registration #14	2017-02-27	114.434 mi
Registration #15	2018-05-01	115.419 mi
Registration #16	2019-05-01	116.404 mi
Registration #17	2020-05-01	117.389 mi
Registration #18	2021-05-01	118.374 mi
Registration #19	2022-05-01	119.359 mi
Registration #20	2023-05-01	120.344 mi
Registration #21	2024-05-01	121.329 mi
Registration #22	2025-05-01	122.314 mi
Registration #23	2026-05-01	123.299 mi
Registration #24	2027-05-01	124.284 mi
Registration #25	2028-05-01	125.269 mi
Registration #26	2029-05-01	126.254 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1778 mm
Height	1702 mm
Length	4267 mm
Wheel base	2490 mm
Kerb weight	1485 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	1CD0093728