



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 STYLE
Colour	Grey
Year of manufacture	2015
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2



Date	2022-02-19
Pictures	22
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-18
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-17
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	37
Total items failed	0

MOT #10	2024-01-26 11:51
MOT test number	912698213355
Result	✓ Passed
Next expiry date	2025-02-17
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2023-02-01 17:37
MOT test number	289874180870
Result	✓ Passed

MOT #8	2023-01-30 11:35
MOT test number	222900069747
Result	✗ Failed
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
MAJOR	Offside Rear Parking brake inoperative on one side (1.4.1 (a))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #7** 2022-02-18 09:40**MOT test number** 370290590889**Result** ✓ Passed**MOT #6** 2022-02-16 17:03**MOT test number** 562316597286**Result** ✗ Failed**DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2021-12-22 15:37**MOT test number** 485990429198**Result** ✗ Failed**MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Rear fog lamp switch not operating in accordance with the requirements (4.5.3 (a))**Advice** Nearside Rear parking brake excessive lagging outside failure criteria**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Front fog lights and tell tale not working manufactured prior to failure criteria**MAJOR** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick metal to metal (1.1.13 (a) (ii))**MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm thin edge (5.2.3 (e))

**MOT #4** 2020-12-18 17:03**MOT test number** 349149298388**Result** ✓ Passed**Advice** Nearside Rear parking brake lagging requires further investigation, meets minimum efficiency**Advice** Offside Front fog light not working. Prior to failure criteria date**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #3** 2020-12-18 14:58**MOT test number** 463005626549**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front fog light not working. Prior to failure criteria date**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**DANGEROUS** Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear parking brake lagging requires further investigation, meets minimum efficiency**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))



MOT #2	2019-06-24 10:10
MOT test number	496000449305
Result	✓ Passed
<div>Advice Vehicles internal headlight adjuster altered to recheck lights</div>	

MOT #1	2018-06-25 09:13
MOT test number	476236912501
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
17 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2015-03-29
Current registration	
Plate since	2015-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-04-30
Last registration	2024-01-26
Complete history	See info



Registration #1	2015-04-30	29 mi
Registration #2	2018-06-25	18.682 mi
Registration #3	2019-06-24	46.563 mi
Registration #4	2020-12-18	82.969 mi
Registration #5	2020-12-18	82.969 mi
Registration #6	2021-12-22	111.981 mi
Registration #7	2022-02-16	112.806 mi
Registration #8	2022-02-16	112.806 mi
Registration #9	2022-02-16	112.806 mi
Registration #10	2022-02-16	112.806 mi
Registration #11	2022-02-16	112.806 mi
Registration #12	2022-02-16	112.806 mi
Registration #13	2022-02-16	112.806 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

G4FAFZ102892