



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SPORT 5 STR
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2


Date	2022-01-26
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-27
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	19
Total items failed	4

MOT #16	2023-12-29 11:56
MOT test number	429509081608
Result	✓ Passed
Next expiry date	2025-01-25

MOT #15	2023-01-19 13:44
MOT test number	738524541537
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-01-19 13:44
MOT test number	203453328772
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-01-26 12:32
MOT test number	676261291312
Result	✓ Passed

**MOT #12** 2022-01-25 16:09**MOT test number** 718580135460**Result** ✗ Failed

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11 2021-03-27 09:58**MOT test number** 531317271815**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10 2020-03-25 12:06**MOT test number** 794599304149**Result** ✓ Passed**MOT #9** 2020-03-25 12:06**MOT test number** 170420268378**Result** ✗ Failed

Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #8 2019-03-26 14:29**MOT test number** 591594632352**Result** ✓ Passed**MOT #7** 2017-10-23 15:16**MOT test number** 888391082036**Result** ✓ Passed

**MOT #6** 2016-04-29 12:02**MOT test number** 245586106809**Result** ✓ Passed**Advice** Emission not tested has low rearing**Advice** Under tray fitted**MOT #5** 2016-04-29 10:19**MOT test number** 788150234884**Result** ✗ Failed**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Emission not tested has low rearing**Fail** Nearside Rear Direction indicator has less than 50% of the light sources illuminating (1.4.A.2c)**Advice** Under tray fitted**MOT #4** 2015-10-14 10:45**MOT test number** 912235975821**Result** ✓ Passed**MOT #3** 2014-10-14 12:38**MOT test number** 316417984449**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Near side rear , offside front and rear tyres wearing more on inner edges**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-10-16 09:42
MOT test number	615269783230
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	O/s/f tyre getting low on tread
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2012-10-02 11:56
MOT test number	486196972279
Result	✓ Passed
Notice	Offside rear brake disc corroded on outer face



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	KN59KOW
Plate since	2019-06-29
Current registration	KN59KOW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-15
Last registration	2023-12-29
Complete history	See info



Registration #1	2009-10-15	8 mi
Registration #2	2012-10-02	29.405 mi
Registration #3	2013-10-16	36.713 mi
Registration #4	2014-10-14	45.301 mi
Registration #5	2015-10-14	51.428 mi
Registration #6	2016-04-29	55.278 mi
Registration #7	2016-04-29	55.278 mi
Registration #8	2017-10-23	61.955 mi
Registration #9	2019-03-26	67.392 mi
Registration #10	2020-03-25	72.603 mi
Registration #11	2020-03-25	72.603 mi
Registration #12	2020-03-25	72.603 mi
Registration #13	2020-03-25	72.603 mi
Registration #14	2020-03-25	72.603 mi
Registration #15	2020-03-25	72.603 mi
Registration #16	2020-03-25	72.603 mi
Registration #17	2020-03-25	72.603 mi
Registration #18	2020-03-25	72.603 mi
Registration #19	2020-03-25	72.603 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007