



**MA06VAV**

report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI S LINE
Colour	Black
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	10.2 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg



**MOT history**

<b>MOT #20</b>	2021-07-02 13:35
<b>MOT test number</b>	536114625124
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-07-01
<b>Advice</b>	Nsr/osr coil spring corroded

<b>MOT #19</b>	2020-02-28 16:54
<b>MOT test number</b>	282862944423
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
<b>Advice</b>	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge On 1.7mm (5.2.3 (e))

**MOT #18**

2020-02-28 14:12

**MOT test number**

899421383216

**Result****✗ Failed**

- Fail** Offside Front Headlamp insecure (4.1.1 (c))
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))
- Fail** Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Brake performance not tested (1.2.1 (g))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Front Headlamp insecure (4.1.1 (c))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge On 1.7mm (5.2.3 (e))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #17**

2019-03-01 15:26

**MOT test number**

606371011737

**Result****✓ Passed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides rear (1.1.14 (a) (ii))

**MOT #16**

2019-03-01 09:55

**MOT test number**

431312598309

**Result**

✗ Failed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides rear (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge nail in side at top (5.2.3 (e))**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure small lump outter edge (5.2.3 (d) (ii))**Fail** Windscreen washer provides insufficient washer liquid near side not working (3.5 (a))**MOT #15**

2018-01-30 13:43

**MOT test number**

553481175414

**Result**

✓ Passed

**Advice** Rear Brake hose slightly deteriorated both sides (3.6.B.4d)**Advice** Oil leak**MOT #14**

2018-01-29 16:52

**MOT test number**

602820946108

**Result**

✗ Failed

**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake hose slightly deteriorated both sides (3.6.B.4d)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Oil leak**MOT #13**

2017-02-28 10:22

**MOT test number**

342919343181

**Result**

✓ Passed

**Advice** Offside Rear Tyre cracking

**MOT #12** 2017-02-23 09:41**MOT test number** 641109459146**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre cracking**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #11** 2015-12-14 12:32**MOT test number** 207549632347**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit wearing on inner edge (4.1.E.1)**MOT #10** 2015-12-14 12:32**MOT test number** 347771871702**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear Tyre worn close to the legal limit wearing on inner edge (4.1.E.1)**MOT #9** 2014-12-05 11:00**MOT test number** 239739934319**Result** ✓ Passed**MOT #8** 2014-12-05 09:40**MOT test number** 227299134311**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**MOT #7** 2013-12-18 14:10**MOT test number** 248062853354**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-12-18 10:55**MOT test number** 578662053363**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2012-12-18 13:58**MOT test number** 297803652352**Result** ✓ Passed**MOT #4** 2012-03-12 14:43**MOT test number** 139102972440**Result** ✓ Passed**MOT #3** 2011-04-01 10:46**MOT test number** 279671991083**Result** ✓ Passed



MOT #2	2010-04-01 13:11
MOT test number	392101990011
Result	✓ Passed

MOT #1	2009-03-25 10:53
MOT test number	801444089088
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-28
Current registration	
Plate since	2019-06-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-24
Last registration	2021-07-02
Complete history	<a href="#">See info</a>



Registration #1	2006-03-24	20 mi
Registration #2	2009-03-25	53.956 mi
Registration #3	2010-04-01	64.768 mi
Registration #4	2011-04-01	76.710 mi
Registration #5	2012-03-12	84.548 mi
Registration #6	2012-12-18	89.616 mi
Registration #7	2013-12-18	101.080 mi
Registration #8	2013-12-18	101.097 mi
Registration #9	2014-12-05	108.285 mi
Registration #10	2014-12-05	108.285 mi
Registration #11	2015-12-14	117.782 mi
Registration #12	2016-01-01	117.782 mi
Registration #13	2016-01-01	117.782 mi
Registration #14	2016-01-01	117.782 mi
Registration #15	2016-01-01	117.782 mi
Registration #16	2016-01-01	117.782 mi
Registration #17	2016-01-01	117.782 mi
Registration #18	2016-01-01	117.782 mi
Registration #19	2016-01-01	117.782 mi
Registration #20	2016-01-01	117.782 mi
Registration #21	2016-01-01	117.782 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2808 mm
Kerb weight	1530 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	BRE 023171