



report date: 2024-03-28

General information

Make	KIA
Model	VENGA 2 ECODYNAMICS
Colour	White
Year of manufacture	2014
Top speed	103 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 4.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-12
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-17
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	22
Total items failed	5

MOT #12 2023-09-14 10:46

MOT test number 620964161825

Result ✓ Passed

Next expiry date 2024-09-17

**Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11 2023-09-04 10:07

MOT test number 834845842983

Result ✗ Failed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))

**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #10 2022-09-12 14:29

MOT test number 213059927567

Result ✓ Passed

**MOT #9** 2022-09-12 13:08**MOT test number** 170056652219**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2021-09-14 15:53**MOT test number** 390569992433**Result** ✓ Passed**MOT #7** 2020-09-18 15:50**MOT test number** 279729484985**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2019-05-30 14:18**MOT test number** 146155022664**Result** ✓ Passed**MOT #5** 2018-06-06 12:10**MOT test number** 342971270698**Result** ✓ Passed

**MOT #4** 2018-06-06 12:10**MOT test number** 238233257780**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #3** 2017-06-02 14:46**MOT test number** 673917398672**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit and bald on outer edge (4.1.E.1)**Advice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit and bald on outer edge (4.1.E.1)**MOT #2** 2017-06-02 14:46**MOT test number** 382011113341**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit and bald on outer edge (4.1.E.1)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Tyre worn close to the legal limit and bald on outer edge (4.1.E.1)**Advice** Items removed from driver's view prior to test



MOT #1	2017-05-31 12:55
MOT test number	312112225285
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Shock absorber has a serious fluid leak (2.7.3)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-04-16
Last registration	2023-09-14
Complete history	<a href="#">See info</a>



Registration #1	2014-04-16	23 mi
Registration #2	2017-05-31	22.579 mi
Registration #3	2017-06-02	22.582 mi
Registration #4	2017-06-02	22.582 mi
Registration #5	2018-06-06	26.013 mi
Registration #6	2018-06-06	26.013 mi
Registration #7	2019-05-30	29.509 mi
Registration #8	2019-05-30	29.517 mi
Registration #9	2019-05-30	29.517 mi
Registration #10	2019-05-30	29.517 mi
Registration #11	2019-05-30	29.517 mi
Registration #12	2019-05-30	29.517 mi
Registration #13	2019-05-30	29.517 mi
Registration #14	2019-05-30	29.517 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1343 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FAEZ563660