




report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-09-22
Pictures	48
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-14
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	48
Total items failed	2

MOT #14	2022-11-15 10:34
MOT test number	644338562775
Result	✓ Passed
Next expiry date	2023-11-14
Advice	Offside Rear Nail in tyre
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2022-11-08 15:20

**MOT test number**

263768753438

**Result****✗ Failed**

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Brake performance not tested Due to condition of tyre(S) (1.2.1 (g))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- MAJOR** Reversing lamp inoperative (4.6.1 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #12**

2021-09-30 10:52

**MOT test number**

216508654357

**Result****✓ Passed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #11**

2021-09-27 12:26

**MOT test number**

592596127310

**Result****✗ Failed**

- Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10**

2021-02-03 16:03

**MOT test number**

524618197566

**Result****✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2021-02-03 10:30

**MOT test number**

147856806847

**Result****✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2020-01-21 10:26**MOT test number** 225662214659**Result** ✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Central Rear wiring to the towing wiring insecure.

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #7** 2020-01-21 10:26**MOT test number** 977667948474**Result** ✗ Failed

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Central Rear wiring to the towing wiring insecure.

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2019-02-06 12:17**MOT test number** 429835291258**Result** ✓ Passed

**Advice** Oil leak, but not excessive engine oil leaks (8.4.1 (a) (i))

**Advice** Nearside Rear Nail in tyre

**MOT #5** 2019-02-06 10:28**MOT test number** 130679226862**Result** ✗ Failed

**MAJOR** Offside Front All position lamps not working (4.2.1 (a))

**Advice** Nearside Rear Nail in tyre

**Advice** Oil leak, but not excessive engine oil leaks (8.4.1 (a) (i))

**MOT #4** 2017-11-16 14:07**MOT test number** 656538039997**Result** ✓ Passed**Advice** Oil leak**MOT #3** 2017-11-16 10:33**MOT test number** 345762820391**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Oil leak**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2016-11-29 13:16**MOT test number** 514218745447**Result** ✓ Passed**MOT #1** 2015-11-30 13:07**MOT test number** 836861117528**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 October 2023

✕  
MOT

Expired:  
14 November 2023

Tax status	Expired at 31 October 2023
Days left	181 days too late
MOT expiry date	14 November 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-






Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YB62GZL
Plate since	2024-03-29
Current registration	 YB62GZL
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-02-27
Last registration	2022-11-15
Complete history	<a href="#">See info</a>



Registration #1	2013-02-27	15 mi
Registration #2	2015-11-30	23.085 mi
Registration #3	2016-11-29	31.546 mi
Registration #4	2017-11-16	37.575 mi
Registration #5	2017-11-16	37.575 mi
Registration #6	2019-02-06	48.304 mi
Registration #7	2019-02-06	48.304 mi
Registration #8	2020-01-21	58.657 mi
Registration #9	2020-01-21	58.657 mi
Registration #10	2020-01-21	58.657 mi
Registration #11	2020-01-21	58.657 mi
Registration #12	2020-01-21	58.657 mi
Registration #13	2020-01-21	58.657 mi
Registration #14	2020-01-21	58.657 mi
Registration #15	2020-01-21	58.657 mi
Registration #16	2020-01-21	58.657 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ