





report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D4 SE LUX
Colour	Silver
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	175 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.984 сс
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-15

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



AK62EYL

report date: 2024-03-29

B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2024-09-27
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #12	2023-09-27 12:54
MOT test number	368527110148
Result	✓ Passed
Next expiry date	2024-09-27

MOT #11	2022-09-28 14:13
MOT test number	564572618536
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2021-09-16 09:24
MOT test number	837140510100
Result	✓ Passed

MOT #9		2020-09-16 15:08
MOT test	number	776924245282
Result		✓ Passed
Advice	Nearside Rear Nail in tyre	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



Result

AK62EYL report date: 2024-03-29

MOT #8 2019-09-23 15:40

665557576105 **MOT** test number

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear parking brake has Ittle reserve travel

MOT #7 2019-09-23 09:57

MOT test number 880576853110

X Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Rear parking brake has Ittle reserve travel **Advice**

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2018-09-19 10:40

MOT test number 271686786195

Result ✓ Passed

MOT #5 2018-09-19 10:40

MOT test number 305557789960

Result × Failed

Pass with rectification Nearside Front Outline marker lamp not working (4.2.1 (a))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

MOT #4 2017-09-22 12:51

258606074965 **MOT** test number

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #3

MOT test number

Passed

MOT #2

MOT test number

MOT test number

MOT test number

S15877076192

Result

Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #1

MOT test number

Result

Advice Offside rear tyre low on inside edge

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)

	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		7
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-24
Last registration	2023-09-27
Complete history	See info



Registration #1	2012-09-24	29 mi
Registration #2	2015-09-16	26.431 mi
Registration #3	2016-09-05	33.954 mi
Registration #4	2016-09-05	33.954 mi
Registration #5	2017-09-22	43.994 mi
Registration #6	2018-09-19	52.375 mi
Registration #7	2018-09-19	52.375 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		
Registration #13		71.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	2025 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1789 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Engine number

1109685