



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SPORT
Colour	Blue
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-10-14
Pictures	35
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-29
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	22
Total items failed	2

MOT #16 2023-11-28 16:48

MOT test number 239748635519

Result ✓ Passed

Next expiry date 2024-11-29

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Close to limit and very low on edges (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Wishbone rear bush (5.3.4 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Close to limit and very low on edges (5.2.3 (e))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2022-11-28 12:11

MOT test number 212911395951

Result ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #14 2021-11-30 14:39

MOT test number 635330921848

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-06-24 15:02**MOT test number** 876565532865**Result** ✓ Passed**MOT #12** 2021-06-24 15:02**MOT test number** 229110845310**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11** 2020-06-16 09:13**MOT test number** 162992337314**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**MOT #10** 2019-06-26 16:00**MOT test number** 694397530255**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-05-22 11:00**MOT test number** 579382013293**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8** 2017-05-24 12:18**MOT test number** 939650392471**Result** ✓ Passed**MOT #7** 2016-06-21 12:08**MOT test number** 497979724875**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2015-06-04 11:21**MOT test number** 525905955188**Result** ✓ Passed**Notice** Rear tyres worn close to limit**Notice** Rear tyres perished**MOT #5** 2014-05-21 14:17**MOT test number** 296311744434**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-05-01 12:11**MOT test number** 438891423161**Result** ✓ Passed**MOT #3** 2012-04-24 17:30**MOT test number** 756635312112**Result** ✓ Passed



MOT #2	2012-04-24 10:44
MOT test number	229725512148
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #1	2011-04-01 11:05
MOT test number	745981391016
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-05-07
Last registration	2023-11-28
Complete history	See info



Registration #1	2008-05-07	18 mi
Registration #2	2011-04-01	34.101 mi
Registration #3	2012-04-24	39.266 mi
Registration #4	2012-04-24	39.266 mi
Registration #5	2013-05-01	48.854 mi
Registration #6	2014-05-21	52.902 mi
Registration #7	2015-06-04	55.784 mi
Registration #8	2016-06-21	58.099 mi
Registration #9	2017-05-24	60.336 mi
Registration #10	2018-05-29	61.377 mi
Registration #11	2019-05-29	61.377 mi
Registration #12	2020-05-29	61.377 mi
Registration #13	2021-05-29	61.377 mi
Registration #14	2022-05-29	61.377 mi
Registration #15	2023-05-29	61.377 mi
Registration #16	2024-05-29	61.377 mi
Registration #17	2025-05-29	61.377 mi
Registration #18	2026-05-29	61.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	473928
---------------	--------