



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 2900 L1H1 CDTI DCB SPORTIVE
Colour	Blue
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	46.3 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-16
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-07
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #7 2024-03-08 08:56

MOT test number 947287282182

Result ✓ Passed

Next expiry date 2025-03-07

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Fluid leak, but not excessive gearbox (8.4.1 (a) (i))

MOT #6 2024-03-07 10:53

MOT test number 623441979711

Result ✗ Failed**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Fluid leak, but not excessive gearbox (8.4.1 (a) (i))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #5 2023-02-11 15:58

MOT test number 679829070590

Result ✓ Passed

**MOT #4** 2022-03-08 09:31**MOT test number** 353467924012**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Tyre slightly damaged/cracking or perishing ALL 4 TYRES HAVE CRACKING/PERISHING IN TREAD BLOCK (5.2.3 (d) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt NSR AND OSR**MOT #3** 2022-02-28 14:28**MOT test number** 274550099601**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Child Seat fitted not allowing full inspection of adult belt NSR AND OSR**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Tyre slightly damaged/cracking or perishing ALL 4 TYRES HAVE CRACKING/PERISHING IN TREAD BLOCK (5.2.3 (d) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #2** 2021-03-02 12:33**MOT test number** 318937923780**Result** ✓ Passed**MOT #1** 2019-07-18 11:50**MOT test number** 753154887198**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-28
Last registration	2024-03-08
Complete history	See info



Registration #1	2016-09-28	15 mi
Registration #2	2019-07-18	89.075 mi
Registration #3	2021-03-02	103.410 mi
Registration #4		
Registration #5	2022-02-28	115.115 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1770 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	R9M MB - C067880LWU