





report date: 2024-03-29

#### General information

Make	NISSAN
Model	MICRA VISIA
Colour	White
Year of manufacture	2015
Top speed	105 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



## Internet history

#### Entry 2

Date	2021-12-07
Pictures	0
Listing price	<u>View report</u>

#### source: autotrader.co.uk

#### Entry 1

, -		
Date	2021-02-03	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history
-------------

MOT expiry date	2025-03-07
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	4
Total items failed	4

MOT #8	2024-03-04 10:58
MOT test number	384182545215
Result	✓ Passed
Next expiry date	2025-03-07

MOT #7	2023-03-08 14:56
MOT test number	358016754830
Result	✓ Passed

MOT #6	2021-12-07 09:48
MOT test number	142203630294
Result	✓ Passed

MOT #5		2021-03-10 15:17
MOT test	number	873291151737
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2020-03-19 10:27
MOT test number	250044001767
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2019-03-22 11:17

**MOT test number** 849407546193

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #2 2018-09-21 10:17

**MOT test number** 588210161253

MOT #1 2018-09-20 10:06

**MOT test number** 903202910507

Result × Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	7 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
**************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	NE SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-29
Last registration	2024-03-04
Complete history	See info



Registration #1	2015-09-29	11 mi
Registration #2	2018-09-20	29.285 mi
Registration #3	2018-09-21	29.286 mi
Registration #4	2019-03-22	31.067 mi
Registration #5	2020-03-19	38.266 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 10/11



## Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	1665 mm
Height	1535 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg

# Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number 849420B