





report date: 2024-03-29

General information

Make	HONDA
Model	HR-V I-VTEC SE
Colour	Blue
Year of manufacture	2017
Top speed	119 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	155 Nm at 4.600 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-05-27
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	5
Total items failed	2

MOT #8	2023-05-26 11:07
MOT test number	691256233908
Result	✓ Passed
Next expiry date	2024-05-27
Advice Rear Tyre worn close to legal limit/worn on edge advise both rear tyre 2.5/3mm (5.2.3 (e))	es wearing low on between

MOT #7	2022-05-23 09:52
MOT test number	289173734318
Result	✓ Passed
Advice Offside Front Tyre slightly damaged (5.2.3 (d) (ii))	

MOT #6	2021-05-28 15:41
MOT test number	590471648820
Result	✓ Passed

MOT #5	2021-05-28 15:41
MOT test number	757453700398
Result	X Failed
Pass with rectification	Offside Front Brake hose connection leaking on a hydraulic braking system hose
to calliper (1.1.12 (c) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-01-26 08:52

MOT test number 497572591780

Result ✓ Passed

MOT #3 2020-05-28 13:58

MOT test number 112834078211

Result ✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2 2020-05-28 11:51

MOT test number 541064428679

Result X Failed

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1 2020-05-23 11:21

MOT test number 791944626761

Result ✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

O		1-1-4	
- 1114	vner	піст	$\alpha r v$
\cup	VIICI	IIIJU	ע וט.

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		Α

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		

	More info	>
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		
Current registration	NK MA	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-31
Last registration	2023-05-26
Complete history	See info



Registration #1	2017-05-31	28 mi
Registration #2	2020-05-28	22.869 mi
Registration #3	2020-05-28	22.869 mi
Registration #4	2021-01-26	26.854 mi
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	72%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1605 mm
Length	4294 mm
Wheel base	2610 mm
Kerb weight	1313 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	L15B41026044

CarCheck.co.uk page 11/11