



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER
Colour	Black
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-04-16
Pictures	8
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-21
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	37
Total items failed	15

**MOT #18** 2024-02-12 09:03**MOT test number** 363516257527**Result** ✓ Passed**Next expiry date** 2025-02-21**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2024-02-12 09:03**MOT test number** 289595886677**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #16** 2023-02-15 14:59**MOT test number** 855634722675**Result** ✓ Passed**MOT #15** 2023-02-15 12:41**MOT test number** 370259065311**Result** ✗ Failed**Fail** Offside Headlamp aim too low (4.1.2 (a))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #14** 2023-02-13 13:43**MOT test number** 765298521599**Result** ✗ Failed**Advice** Oil leak, but not excessive Transmission (8.4.1 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))**MOT #13** 2022-02-22 09:47**MOT test number** 596632546257**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))**Advice** Towball/hitch not fitted at time of test**Advice** Tyre worn close to legal limit/worn on edge both fronts approaching wearbars (5.2.3 (e))

**MOT #12** 2021-05-12 09:09**MOT test number** 622421718245**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items on rear seats**MOT #11** 2021-05-10 14:06**MOT test number** 472287127770**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Items on rear seats**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #10** 2020-04-29 08:56**MOT test number** 417462732673**Result** ✓ Passed**MOT #9** 2020-04-24 11:29**MOT test number** 140038210023**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively both blades (3.4 (b) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Advice** Tyre slightly damaged/cracking or perishing both rears (5.2.3 (d) (ii))

**MOT #8** 2019-04-29 14:36**MOT test number** 905668060639**Result** ✓ Passed

- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2019-04-24 08:57**MOT test number** 911267421416**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #6** 2018-05-10 11:16**MOT test number** 296514941135**Result** ✓ Passed

- Advice** Tyre worn close to the legal limit both front worn close to wearbars (4.1.E.1)
- Advice** Towball/hitch not fitted at time of test

**MOT #5** 2017-04-21 11:43**MOT test number** 464193465109**Result** ✓ Passed

- Advice** Windscreen cracked

**MOT #4** 2017-04-19 11:29**MOT test number** 921928496303**Result** ✗ Failed**Fail** Brake hydraulic reservoir cap missing (3.6.G.1a)**Fail** Brake fluid warning lamp illuminated (3.6.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Windscreen cracked**MOT #3** 2016-04-12 12:14**MOT test number** 597781014350**Result** ✓ Passed**MOT #2** 2015-05-01 13:54**MOT test number** 126471025110**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-04-29 12:57**MOT test number** 225999914101**Result** ✓ Passed**Notice** Nail in offside front tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
21 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	21 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	KW11VGK
Plate since	2019-09-28
Current registration	KW11VGK
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-05-19
Last registration	2024-02-12
Complete history	<a href="#">See info</a>



Registration #1	2011-05-19	24 mi
Registration #2	2014-04-29	20.150 mi
Registration #3	2015-05-01	25.466 mi
Registration #4	2016-04-12	30.696 mi
Registration #5	2017-04-19	40.319 mi
Registration #6	2017-04-21	40.321 mi
Registration #7	2018-05-10	51.210 mi
Registration #8	2019-04-24	61.294 mi
Registration #9	2019-04-29	61.429 mi
Registration #10	2020-04-24	72.631 mi
Registration #11	2020-05-20	83.833 mi
Registration #12	2021-05-20	95.035 mi
Registration #13	2022-05-20	106.237 mi
Registration #14	2023-05-20	117.439 mi
Registration #15	2024-05-20	128.641 mi
Registration #16	2025-05-20	139.843 mi
Registration #17	2026-05-20	151.045 mi
Registration #18	2027-05-20	162.247 mi
Registration #19	2028-05-20	173.449 mi
Registration #20	2029-05-20	184.651 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	A023I929