



report date: 2024-03-29

General information

Make	CITROEN
Model	C4 PURETECH FLAIR S/S
Colour	Black
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	100 g/km
CO2 label	A





Internet history

Entry 3

Date	2023-07-07
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 2

Date	2021-09-30
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-04-02
<b>MOT pass rate</b>	60 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	16
<b>Total items failed</b>	4

**MOT #10** 2024-03-25 12:16**MOT test number** 850754856547**Result** ✓ Passed**Next expiry date** 2025-04-02

- Advice** Rear Tyre worn close to legal limit/worn on edge both rear tyres heavily worn , 2mm remaining (5.2.3 (e))
- Advice** Leak from washer pump pipe
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both rear bush's deteriorated (5.3.4 (a) (i))

**MOT #9** 2024-03-25 12:16**MOT test number** 545934808174**Result** ✗ Failed

- Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both rear bush's deteriorated (5.3.4 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge both rear tyres heavily worn , 2mm remaining (5.2.3 (e))
- Advice** Leak from washer pump pipe
- Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8** 2023-04-03 16:02**MOT test number** 619870522451**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tread on 3mm and cracking. (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tread on 3mm and cracking. (5.2.3 (e))**MOT #7** 2023-03-31 12:22**MOT test number** 569840831974**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tread on 3mm and cracking. (5.2.3 (e))**MAJOR** Front Windscreen washer not working (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tread on 3mm and cracking. (5.2.3 (e))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment No reserve travel.  
(1.1.6 (c))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #6** 2022-03-25 10:07**MOT test number** 195727742778**Result** ✓ Passed**MOT #5** 2021-03-01 08:09**MOT test number** 206455918679**Result** ✓ Passed**MOT #4** 2020-02-18 14:15**MOT test number** 317746509145**Result** ✓ Passed



MOT #3	2020-02-18 14:15
MOT test number	532350696344
Result	✗ Failed
Pass with rectification	Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Pass with rectification	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #2	2019-03-09 12:23
MOT test number	274779347138
Result	✓ Passed

MOT #1	2019-03-08 11:13
MOT test number	822597284054
Result	✗ Failed
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
2 April 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	2 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 KY16EKC
Plate since	2019-03-29
Current registration	 KY16EKC
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2016-03-17
Last registration	2024-03-25
Complete history	<a href="#">See info</a>



Registration #1	2016-03-17	25 mi
Registration #2	2019-03-08	39.591 mi
Registration #3	2019-03-09	39.591 mi
Registration #4	2020-02-18	44.883 mi
Registration #5	2020-02-18	44.883 mi
Registration #6	2020-02-18	44.883 mi
Registration #7	2021-03-01	47.124 mi
Registration #8	2021-03-01	47.124 mi
Registration #9	2021-03-01	47.124 mi
Registration #10	2021-03-01	47.124 mi
Registration #11	2021-03-01	47.124 mi
Registration #12	2021-03-01	47.124 mi
Registration #13	2021-03-01	47.124 mi
Registration #14	2021-03-01	47.124 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1020 kg
Max. allowed weight	1555 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XV120205743