



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Blue
Year of manufacture	2018
Top speed	137 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	34.5 mpg
CO2 emission	162 g/km
CO2 label	G






Internet history

Entry 3




Date	2021-08-23
Pictures	10
Listing price	View report



source: [heycar.co.uk](https://www.heycar.co.uk)

Entry 2

Date	2021-07-26
Pictures	10
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)

Entry 1

Date	2021-07-13
Pictures	0
Listing price	View report

source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-05-15
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #4 2023-04-27 14:36**MOT test number** 661861830047**Result** Passed**Next expiry date** 2024-05-15**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2023-04-26 08:51**MOT test number** 878868374722**Result** Failed**Fail** Nearside Rear Rear reflector missing (4.8.2 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #2	2022-05-14 09:59
MOT test number	742457968721
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Advice	Tyre slightly damaged/cracking or perishing All tyres perished (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #1	2021-05-05 11:14
MOT test number	817533396535
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
15 May 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	15 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-16
Last registration	2023-04-27
Complete history	See info



Registration #1	2018-05-16	28 mi
Registration #2	2021-05-05	19.965 mi
Registration #3	2023-05-20	20.277 mi
Registration #4	2023-05-20	20.277 mi
Registration #5	2023-05-20	20.277 mi
Registration #6	2023-05-20	20.277 mi
Registration #7	2023-05-20	20.277 mi
Registration #8	2023-05-20	20.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Max. allowed weight	2750 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	2561992