



report date: 2024-03-28

General information

Make	FIAT
Model	500L MULTIJET POP STAR
Colour	Red
Year of manufacture	2013
Top speed	102 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 2


Date	2023-03-23
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-07
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-22
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	44
Total items failed	3

MOT #12	2023-10-23 10:28
MOT test number	716945302555
Result	✓ Passed
Next expiry date	2024-10-22

MOT #11	2022-09-08 14:35
MOT test number	281783399679
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2022-09-06 08:21

**MOT test number**

789194537306

**Result****✗ Failed**

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front daytime running lamp inoperative
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2022-08-30 13:53

**MOT test number**

864213969552

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Offside Front daytime running lamp inoperative
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2021-10-07 12:08

**MOT test number**

843639169782

**Result****✓ Passed**

**MOT #7**

2020-08-29 09:11

**MOT test number**

214104058083

**Result**

✓ Passed

- Advice** Nearside Rear tyre age cracking
- Advice** Nearside Rear quarter panel damaged and protruding slightly
- Advice** Nearside Rear brake caliper handbrake lever not returning to stop
- Advice** Both front wiper blades smearing
- Advice** Both rear handbrake cable outer casing split

**MOT #6**

2020-08-27 10:56

**MOT test number**

532616406225

**Result**

✗ Failed

- Advice** Nearside Rear brake caliper handbrake lever not returning to stop
- Advice** Nearside Rear tyre age cracking
- Advice** Oil light flashing on dash
- MAJOR** Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a))
- Advice** Rear wiper blade split
- MAJOR** Nearside Front Headlamp insecure (4.1.1 (c))
- Advice** Both rear handbrake cable outer casing split
- Advice** Nearside Front tyre deep cut in sidewall cords not visible
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Both front wiper blades smearing
- MAJOR** Exhaust fumes entering cabin suspect possible exhaust or injector leaking (6.1.2 (b) (i))
- Advice** Nearside Rear quarter panel damaged and protruding slightly

**MOT #5** 2019-09-07 08:45**MOT test number** 945394486910**Result** ✓ Passed

- Advice** Nearside Front daytime running light not working
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Both front brake discs excessively lipped and corroded
- Advice** Nearside Rear quarter panel and front door damaged
- Advice** Nearside Rear tyre age cracking

**MOT #4** 2019-09-07 08:45**MOT test number** 137369152999**Result** ✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too far to the right (4.1.2 (a))
- Advice** Nearside Rear quarter panel and front door damaged
- Advice** Nearside Rear tyre age cracking
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front daytime running light not working
- Advice** Both front brake discs excessively lipped and corroded

**MOT #3** 2018-10-22 09:44**MOT test number** 914089910485**Result** ✓ Passed



MOT #2	2017-09-09 15:01
MOT test number	185676084719
Result	✓ Passed
MOT #1	2016-09-29 11:57
MOT test number	212771346854
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
22 October 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	22 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-30
Last registration	2023-10-23
Complete history	<a href="#">See info</a>



Registration #1	2013-09-30	27 mi
Registration #2	2016-09-29	41.326 mi
Registration #3	2017-09-09	48.251 mi
Registration #4	2018-10-22	57.758 mi
Registration #5	2019-09-07	68.836 mi
Registration #6	2019-09-07	68.836 mi
Registration #7	2020-08-27	76.335 mi
Registration #8	2020-08-29	76.338 mi
Registration #9	2020-08-29	76.338 mi
Registration #10	2020-08-29	76.338 mi
Registration #11	2020-08-29	76.338 mi
Registration #12	2020-08-29	76.338 mi
Registration #13	2020-08-29	76.338 mi
Registration #14	2020-08-29	76.338 mi
Registration #15	2020-08-29	76.338 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1315 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4939234