



**AV62XHF**


report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI AIRDREAM DSPORT PLUS
Colour	Black
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-05-22
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-25
MOT pass rate	50 %
MOT passed	8
Failed MOT tests	8
Total advice items	31
Total items failed	16

MOT #16 2023-05-23 09:33

MOT test number 308218891206

Result ✓ Passed

Next expiry date 2024-05-25

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15 2023-05-19 08:55

MOT test number 798664437572

Result ✗ Failed

**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Fail** Offside Front Tyre has ply or cords exposed cuts worn inner and outer side walls (5.2.3 (d) (ii))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Fail** Nearside Front Tyre has ply or cords exposed cuts worn inner and outer side walls (5.2.3 (d) (ii))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14**

2022-05-26 14:59

**MOT test number**

515528617914

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, but not excessively both lipped worn (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2022-05-25 08:34

**MOT test number**

446462662576

**Result**

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, but not excessively both lipped worn (1.1.14 (a) (i))

**MOT #12**

2021-05-25 16:52

**MOT test number**

606942709405

**Result**

✓ Passed

**MOT #11**

2021-05-25 16:52

**MOT test number**

457877303866

**Result**

✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**MOT #10** 2020-07-22 12:44**MOT test number** 944342608587**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust bracket broken**MOT #9** 2020-07-22 09:13**MOT test number** 692998804663**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #8** 2019-07-23 15:08**MOT test number** 186942097918**Result** ✓ Passed**MOT #7** 2019-07-23 10:50**MOT test number** 281225922151**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #6**

2018-07-24 14:55

**MOT test number**

846510171610

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear exhaust hanger broken but system adequately supported

**MOT #5**

2018-07-24 07:57

**MOT test number**

446999987171

**Result**

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear exhaust hanger broken but system adequately supported
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

**MOT #4**

2017-05-16 08:07

**MOT test number**

746085148308

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside front tyre has cut in sidewall not through to ply.

**MOT #3** 2017-05-16 08:07**MOT test number** 418600278723**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside front tyre has cut in sidewall not through to ply.**MOT #2** 2015-12-07 12:35**MOT test number** 755614342641**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-12-07 12:35**MOT test number** 938812827237**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
25 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	25 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-01-18
Last registration	2023-05-23
Complete history	<a href="#">See info</a>



Registration #1	2013-01-18	27 mi
Registration #2	2015-12-07	31.365 mi
Registration #3	2015-12-07	31.365 mi
Registration #4	2017-05-16	40.525 mi
Registration #5	2017-05-16	40.525 mi
Registration #6	2018-07-24	47.159 mi
Registration #7	2018-07-24	47.165 mi
Registration #8	2019-07-23	52.744 mi
Registration #9	2019-07-23	52.744 mi
Registration #10	2020-05-20	55.277 mi
Registration #11	2020-05-20	55.277 mi
Registration #12	2020-05-20	55.277 mi
Registration #13	2020-05-20	55.277 mi
Registration #14	2020-05-20	55.277 mi
Registration #15	2020-05-20	55.277 mi
Registration #16	2020-05-20	55.277 mi
Registration #17	2020-05-20	55.277 mi
Registration #18	2020-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFS0006719