





report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA ATLANTIC
Colour	Red
Year of manufacture	2007
Top speed	91 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	97 Nm at 3.000 rpm
Engine capacity	1.086 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-05-19

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-05-17
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #15	2023-05-16 14:16
MOT test number	939716879876
Result	✓ Passed
Next expiry date	2024-05-17
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b	o) (ii))
Minor Offside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	e lamps or light sources
Advice Rear Exhaust mounting defective rear box mount broken off (6.1.2 (a	a))
Advice Front front heat shield loose	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn	to 3 mm (5.2.3 (e))
Minor Nearside Front Lower Suspension arm ball joint dust cover severely de	eteriorated (5.3.4 (b) (i))
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

CarCheck.co.uk page 3/13



MOT #14 2023-05-16 14:16

MOT test number 819187036694

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear Exhaust mounting defective rear box mount broken off (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre worn to 3 mm (5.2.3 (e))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Front front heat shield loose

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

MOT #13 2022-05-18 12:24

MOT test number 781477785662

Result
✓ Passed

MOT #12 2021-04-12 12:11

MOT test number 451688133166

MOT #11 2020-02-15 13:23

MOT test number 135239012617

Result
✓ Passed

CarCheck.co.uk page 4/13



MOT #10

MOT test number

889532954276

Result

Advice
Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice
Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2018-03-13 13:42 **MOT** test number 146760090621 Result ✓ Passed **MOT** #8 2017-03-24 09:34 **MOT test number** 491182326255 Result Passed 2016-03-24 10:05 **MOT #7 MOT** test number 232815051135 Result Passed **MOT #6** 2015-04-24 15:01 **MOT** test number 805374615191 Result Passed **Advice** Front Suspension arm corroded but not seriously weakened (2.4.G.1)

 MOT #5
 2013-11-08 10:38

 MOT test number
 346162213336

 Result
 ✓ Passed

 MOT #4
 2012-11-02 10:36

 MOT test number
 169147402314

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



Pass with rectification

Pass with rectification

PJ57KBZ report date: 2024-03-28

 MOT #3
 2011-11-17 13:38

 MOT test number
 476281521488

 Result
 ✓ Passed

 MOT #2
 2011-11-17 13:38

 MOT test number
 919441621393

 Result
 X Failed

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2010-11-11 11:37

MOT test number 164185410310

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK NEZ
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-11-30
Last registration	2023-05-16
Complete history	See info



Registration #1	2007-11-30	18 mi
Registration #2	2010-11-11	50.683 mi
Registration #3	2011-11-17	57.337 mi
Registration #4	2012-11-02	62.402 mi
Registration #5	2013-11-08	68.102 mi
Registration #6	2015-04-24	70.965 mi
Registration #7	2016-03-24	75.605 mi
Registration #8	2017-03-24	78.782 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Dimensions & weight

Width	1527 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	884 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	G4HG7M274941

CarCheck.co.uk page 13/13