



TOYOTA

NL6ITTJ


report date: 2024-03-29

General information

Make	TOYOTA
Model	URBAN CRUISER D-4D
Colour	Grey
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.800 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-09-15
Pictures	23
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-16
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	61
Total items failed	8

MOT #14	2023-10-17 14:52
MOT test number	440917829176
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2022-10-14 10:14
MOT test number	384891722732
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2021-10-07 10:25
MOT test number	196064852782
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing Cracks in tread. (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Cracks in tread. (5.2.3 (d) (ii))

**MOT #11**

2021-10-06 07:43

**MOT test number**

275229605848

**Result****✗ Failed**

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Cracks in tread. (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Cracks in tread. (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2020-10-06 10:42

**MOT test number**

880616432198

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))
- Advice** Fuel Pipe/s corroded
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Cracked (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #9**

2020-09-28 10:45

**MOT test number**

188412591520

**Result****✗ Failed**

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Emissions not tested (8.2.2.2 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge Cracked (5.2.3 (e))

**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Fuel Pipe/s corroded

**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))

**MOT #8** 2019-09-17 15:06**MOT test number** 156282192516**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear pipe (1.1.11 (c))
- Advice** No print out due to low emissions produced.
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front ball joints leaking grease

**MOT #7** 2018-09-17 09:20**MOT test number** 785718297806**Result** ✓ Passed

- Advice** No print out due to low emissions produced.
- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Brake pipe corroded, covered in grease or other material pipe corroded. (1.1.11 (c))
- Advice** Nearside Front fog lamp lens broken.
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened corrosion on edges. (1.1.14 (a) (ii))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear pipe corroded. (1.1.11 (c))

**MOT #6** 2017-09-14 08:33**MOT test number** 195041809357**Result** ✓ Passed

- Advice** No print out due to low emissions produced.
- Advice** Offside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)
- Advice** Nearside Rear tyre tread deteriorating/cracking.
- Advice** Nearside Front Tyre worn close to the legal limit worn on edges (4.1.E.1)
- Advice** Nearside Rear Brake pipe slightly corroded main pipe. (3.6.B.2c)

**MOT #5** 2016-09-19 14:30**MOT test number** 336111945027**Result** ✓ Passed

- Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear tyre cracking between treads
- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-09-19 14:30**MOT test number** 990900511161**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Front Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**Advice** Nearside Rear tyre cracking between treads**MOT #3** 2015-09-21 12:07**MOT test number** 383009719552**Result** ✓ Passed**MOT #2** 2015-09-21 12:07**MOT test number** 431887764204**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2014-09-12 09:59**MOT test number** 119505254277**Result** ✓ Passed**Notice** O/s/f tyre wearing on edges**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** N/s/f tyre wearing on edges**Notice** Cracks appearing in tread of n/s/r tyre**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
16 October 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		16 October 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-23
Last registration	2023-10-17
Complete history	<a href="#">See info</a>



Registration #1	2011-09-23	25 mi
Registration #2	2014-09-12	20.789 mi
Registration #3	2015-09-21	29.567 mi
Registration #4	2015-09-21	29.567 mi
Registration #5	2016-09-19	35.657 mi
Registration #6	2016-09-19	35.657 mi
Registration #7	2017-09-14	40.796 mi
Registration #8	2018-09-17	47.508 mi
Registration #9	2019-09-17	55.277 mi
Registration #10	2019-09-17	55.277 mi
Registration #11	2019-09-17	55.277 mi
Registration #12	2019-09-17	55.277 mi
Registration #13	2019-09-17	55.277 mi
Registration #14	2019-09-17	55.277 mi
Registration #15	2019-09-17	55.277 mi
Registration #16	2019-09-17	55.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1725 mm
Height	1540 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1265 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1ND1163178